

Pre-Delivery Inspection Form

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any "substitutions" of items referred to in, or to be selected under, the Agreement of Purchase and Sale (APS), Please initial all changes and deletions, As a minimum check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtubs, sinks and toilets
- · Bathroom accessories, it provided
- · Mirrors, countertops and cabinetry
- · Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- · Interior finishes and trim carpentry
- Furnace

Comments .

ONHW-PDIF-01.01

- · Hot water heater, if provided (not a rental)
- Exterior finishes, driveways, walkways, decks and landscaping are complete

OPERATING CONDITION

- Windows, interior and exterior doors (including garage overhead door). Door locks
- · Faucets: kitchen, bathroom, laundry room
- · Exhaust fans (kitchen, bathrooms), if provided
- · Electrical outlets and fixtures
- · Gas fireplaces, incl. circulation fans, if provided
- · Heat Recovery Ventilation system, if provided
- Heating system
- · Hot water heater, if provided (not a rental)
- · Air conditioning system, if provided and if conditions permit

Unit Enrolment # 154 1884

Item #	Room/Location		Description
	GRAT	Koon	BLUE WIRE STICKING OF OR WALL
			SAME SITUATION AT TOP OF STAILWELL
2	ROMA BO	Mism	42 MINON PATCH AKUND CABLE CAP
3	MASTON	BOOK	DO DOOR DOES NOT CLOSE PROPERLY
			CAP ON CABUL ONLY NEWS PARHING.
4	BASEMO	72	WINDOW NOM SUMP PUMP- CHETH
7		-	BOARD NOYTTO SUMPPUMP AT
			BASE LOOKS DARK, POSSIBLE MOULD
			WINDOW OPPOSITE SUMP, OFF HINLE
			ALGO SAME WITH WINDOW NOON STAIKWELL
5	EXPERI	٥ ٨	MI SULENIS ON FRONT DOOR
_			
	, and a second s		

		7-20	
			- MOD 11
-			
			· · · · · · · · · · · · · · · · · · ·

Date \$ 20 07 Lot # 114

