



# Pre-Delivery Inspection Form

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any "substitutions" of items referred to in, or to be selected under, the Agreement of Purchase and Sale (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING	OPERATING CONDITION
<ul style="list-style-type: none"> <li>• Windows, side lights and other glazing. Window and door screens</li> <li>• Bathtubs, sinks and toilets</li> <li>• Bathroom accessories, if provided</li> <li>• Mirrors, countertops and cabinetry</li> <li>• Flooring (hardwood, vinyl, ceramic tiles, carpeting)</li> <li>• Interior finishes and trim carpentry</li> <li>• Furnace</li> <li>• Hot water heater, if provided (not a rental)</li> <li>• Exterior finishes, driveways, walkways, decks and landscaping are complete</li> </ul>	<ul style="list-style-type: none"> <li>• Windows, interior and exterior doors (including garage overhead door). Door locks</li> <li>• Faucets: kitchen, bathroom, laundry room</li> <li>• Exhaust fans (kitchen, bathrooms), if provided</li> <li>• Electrical outlets and fixtures</li> <li>• Gas fireplaces, incl. circulation fans, if provided</li> <li>• Heat Recovery Ventilation system, if provided</li> <li>• Heating system</li> <li>• Hot water heater, if provided (not a rental)</li> <li>• Air conditioning system, if provided and if conditions permit</li> </ul>

### Comments

Item #	Room/Location	Description
1	MASTER BEDROOM	DOORS - TRIM PIECE FOR DOUBLE DOOR NOT PAINTED
2	WASHROOM	MIRRORS NOT INSTALLED
3	BEDROOM #3	CLOSET DOORS UNEVEN NINDA ADJUSTMENT
4	FIRE PLACE	MANTLE NOT PAINTED
5	EXTERIOR	MORE CRUSHED STONE REQUIRED
6	A/C	NOT INSTALLED
Lot 235		
8 Shalom Way		
1459962		