

Vendor/Builder# Purchaser Name :

PDI Page 1 of 1

III TARION 8963 Sg

Enrollment#

Legal Address: Project:

DLS[19] Pratt Hansen Group

Phone Res: Phone Bus: Closing Date: Kanwalijit Jawanda and Kuljit Dhaliwal (289) 752-9168

Plan #:

108 / ESV 2

2014-01-15 Bruno Tidd

Municiaplity:

Inspection Date: 12 Jan 2014

. 45- - ----

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition.

Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS).

Please initial all changes and deletions.As a minimum, check the following:

- DAMAGED, INCOMPLETE OR MISSING

 Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets

- Isathron sinks and tollets
 Bathroom accessories if provided
 Mirrors, counter tops and cabinetry
 Flooring (hardwood, vinyl, ceramic tiles, carpeting)
 Interior finished and trim carpentry

- OPERATING CONDITION Windows, interior and exterior doors including garage overhead doors, door

- locks
 Faucets: Kitchen, bathroom, laundry room
 Exhaust fans (kitchen, bathrooms) if provided
 Electrical outlets and fixtures
 Gas fireplaces, incl.circulation fans, if provided
 Heat Recovery Ventilation system, if provided
 Heating system
 Hot water heater, if provided (not rental)
 Air conditioning system, if provided and if conditions permit

Hot water heater, if provided (not rental) Air conditioning:		g system ater heater, if provided (not rental) nditioning system, if provided and if conditions permit	
	assessed because for example is dirty or inaccessible.		
GENERAL COMMENTS			
INSPECTION START TIME	INSPECTION STARTED AT 12:50 P.M.	A Landson of the Control of the Cont	
NOTE:	TOUCH UPS REQUIRED THROUGH OUT AS INDICATE	da	
NEW TELEPHONE NUMBER	** PURCHASER HAS A NEW PHONE NUMBER - 416	-882-0651,	
MASTER ENSUITE BATH			
WALLS	REPAINT ENSUITE SEVERAL BARE AREAS.		
SHOWER ENCLOSURE	BLACK SPOTS AT TOP OF VINYL ENCLOSURE		
STAIRS			
•	OAK STAIRCASE HAS SEVERAL BLACK STAINS AN STICKING OUT ON BOTH SIDES OF STAIRS. GAP RIGHT SIDE UPPER FLIGHT.STAIRCAS NOT CLEA	IN TRIM ON	
DRYWALL	NOT PAINTED TO LEFT OF STAIRCASE.		
FOYER/HALL			
FLOORING	GROUT STAINS IN CERAMIC FOYER.		
GARDEN/PATIO DOORS			
NOTE:	SCREEN MISSING FROM PATIO DOOR.		
KITCHEN			
FLOORING	CLEAN GROUT SEVERAL AREAS ARE STAINED		
CABINETS	LOWER RIGHT DOOR UNDER SINK STICKS ON COL	INTER TOP.	

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL REPOSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE Verthasers or owners who intend to designate someone to conduct the fauthorizing the designate to significant on their behalf. Builder Representative	WADDANTY RELIBENTS	
Designate's Nume(please print) I the homeowner, confirm that all repair work listed has been completed	Designate's Signature	
	Purchaser	Date

31001-PDIF-01.01

