

PDI Page 1 of 1

Vendor/Builder#

Purchaser Name :

Kevin Wilkes and Christina Dmtruk (416) 836-5558

Phone Res: Phone Bus:

Closing Date: 2013-05-23 Bruno Tidd Inspector:

Enrollment # Legal Address:

Project: Plan #: Lot / Phase #: Municiaplity: DLS[19] Pratt Hansen Group

109 / ESV 2

Inspection Date: 23 May 2013

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition.

Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- · Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets

- Bathroom accessories if provided
 Mirrors, counter tops and cabinetry
 Flooring (hardwood, vinyl, ceramic tiles, carpeting)
 Interior finished and trim carpentry

- Furnace · Hot water heater, if provided (not rental)
- · Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- · Windows, interior and exterior doors including garage overhead doors, door locks · Faucets: Kitchen, bathroom, laundry room

- Faucets: Kitchen, bathroom, laundry fooli
 Exhaust fans (kitchen, bathrooms) if provided
 Electrical outlets and fixtures
 Gas fireplaces, incl.circulation fans, if provided
 Heat Recovery Ventilation system, if provided
 Heating system

- Hot water heater, if provided (not rental)
 Air conditioning system, if provided and if conditions permit

Also list here anything that can't be assessed because for example is dirty or inaccessible.

GENERAL COMMENTS		
INSPECTION START TIME NOTE:	INSPECTION STARTED AT 9: GAS METER NOT INSTALLED. FURNACE NOT WORKING. TEMPORARY HOT WATER TANK INSTALLED.	
NEW TELEPHONE NUMBER	1-647-833-2770	
FOYER/HALL		
WALLS	TWO WALLS NOT SQUARE POWDER ROOM SIDE AND TO LEFT OF HALL CLOSET.	
CLOSET	HANDLE TO BE INSTALLED.	
LIVING ROOM		
FLOORING	HARDWOOD TRANSITION PIECES WRONG COLOUR.	
WALLS	WALL ON RIGHT SIDE OF KITCHEN NOT SQUARE. LOOKS OFF ABOUT 1/2 INCH. WALL AROUND VENT IN CORNER TO LEFT OF KITCHEN NOT SQUARE.	
TRIM	LARGE GAP BETWEEN FLOOR AND TRIM ON EITHER SIDE OF TRANSITION PIECE FROM HALL TO LIVING ROOM.	
EXTERIOR		
PAINT	TO BE COMPLETED	
NOTE:	EAVESTROUGH TO BE COMPLETED. GRADING AND SODDING TO BE COMPLETED. PATIO SLABS FOR ACCESS TO BACK YARD WITH STEPS TO BE INSTALLED.	



THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL REPOSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE V* Purchasers or owners who intend to designate someone to conduct the left.		
Builder Representative	X hall	
Designate's Name(please print) I the homeowner, confirm that all repair work listed has been completed	Designate's Signature	_
	Purchaser	Date

31001-PDIF-01.01