ԻՄԼ ԻՈՈԼ ԻՍՈԱ



PDI Page 1 of 1

Vendor/Builder #

Purchaser Name : Phone Res: Phone Bus: Closing Date:

Inspector:

Ali Topyurek (416) 357-6363

(416) 357-6363 2013-08-08 Bruno Tidd

Enrollment# Legal Address: Project:

DLS[19] Pratt Hansen Group

Plan #: Lot / Phase #: Municiaplity:

61 / ESV 2

Inspection Date: 4 Aug 2013

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition.

Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

· Windows, side lights and other glazing. Window and door screens

· Bathtub sinks and toilets

Bathroom accessories if provided
 Mirrors, counter tops and cabinetry
 Flooring (hardwood, vinyl, ceramic tiles, carpeting)
 Interior finished and trim carpentry

· Hot water heater, if provided (not rental) · Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

Windows, interior and exterior doors including garage overhead doors, door locks

Faucets: Kitchen, bathroom, laundry room

Exhaust fans (kitchen, bathrooms) if provided
 Electrical outlets and fixtures

· Gas fireplaces, incl.circulation fans, if provided

· Heat Recovery Ventilation system, if provided

Heating system
 Hot water heater, if provided (not rental)

· Air conditioning system, if provided and if conditions permit

Also list here anything that can't be assessed because for example is dirty or inaccessible.

GENERAL COMMENTS		
INSPECTION START TIME	INSPECTION STARTED AT 10:00 A.M. TOUCH UPS REQUIRED THROUGH OUT AS INDICATED	
NEW TELEPHONE NUMBER	** PURCHASER HAS A NEW PHONE NUMBER -1-647-400-5201 1-416-367-6363 ** P	
UPPER HALL		
TRIM	LINEN CLOSET DOOR CHIPPED TOP RIGHT CORNER.	
MAIN BATHROOM		
SHOWER ENCLOSURE	SHOWERHEAD HAS A SLOW DRIP.	 -
STAIRS		
- ,	UNFINISHED NOT COATED.	
LIVING ROOM		
	TRANSITION PIECE FROM LIVING ROOM TO KITCHEN WRONG	

FLOORING COLOUR. BAD HARDWOOD SEAMS 4 FT FROM RIGHT PATIO DOOR. MINOR CHIPS AND SCRATCHES IN HARDWOOD.

GARDEN/PATIO DOORS

KITCHEN CERAMIC PURCHASER IS CONCERNED ABOUT GAP AT REAR OF DISHWASHER OPENING. MAY COLLECT WATER AND DEBRIS. WOULD LIKE GROUT OR CAULKING DONE. FLOORING

DOOR EXTREMELY STIFF AND SCREEN MISSING

POWDER ROOM ELECTRICAL/LIGHTIN TWO BULBS BURNT OUT IN LIGHTING TRACK.

BASEMENT WINDOWS SCREENS NOT INSTALLED FLOOR FINISHED VERY POORLY. UNEVEN WITH MANY BUMPS NOTE: AND STREAKS EXTERIOR

DECK NOT BUILT AS YET. EXTERIOR SEASONAL

GRADING SODDING AND EXTERIOR PAINTING TO BE COMPLETED.

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf. DN ush Purchaser Builder Representative Designate's Signature Designate's Name(please print) I the homeowner, confirm that all repair work listed has been completed Purchaser Date

31001-PDIF-01.01

