

PDI Page 1 of 1



Vender/Builder#

34234

Purchaser Name :

Hanadi Bushehri

Phone Res : Phone Bas :

Closing Date:

Inspectora

2011-04-28 Bruno Tidd Eurollment#

Legal Address: Project: Plan #:

Dralled 18525

Pratt Hunsen Group

Municiaplity:

2002 / ESV

Inspection Date: 27 Apr 2011

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition.

Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS).

Please initial all changes and deletions As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens

· Bathtub sinks and toilers

- Batmoon accessories if provided
 Mirrors, counter tops and cabinetry
 Flooring (hardwood, vinyl, ceramic tites, carpeting)
 Interior finished and trim carpentry

OPERATING CONDITION

- · Windows, interior and exterior doors including garage overhead doors, door
- Faucets: Kitchen, bathroom, laundry room
 Exhaust fans (kitchen, bathrooms) if provided
- Electrical outlets and fixtures
- Gas fireplaces, incl. circulation fans, if provided
 Heat Recovery Ventilation system, if provided
 Heating system
 Hot water heater, if provided (not cental)


- Air conditioning system, if provided and if conditions permit

Hot water beater, if provided (not rental)

Exterior finished, driveways, walkways, decks and landscaping

Also list here anything that can't be assessed because for example is dirty or inaccessible. GENERAL COMMENTS

0-01 (220 22 C 0)(1012:113			
INSPECTION START TIME	INSPECTION STARTED AT 8:35		
BEDROOM #2			
TRIM	PAINT REQUIRED AT BOTTOM OF LEDGE OF CIRCULAR WINDOW		
FLOORING	SQUEAK IN FLOOR NEAR DOORWAY		
STAIRS			
-	BROKEN RISER AT TOP OF OAK STAIRS.		
FOYER/HALI.			<u> </u>
FLOORING	CERAMIC CHIPPED AND BROKEN NEAR SMIRY DOOR		
LIVING ROOM			
FLOORING	HARDWOOD SCRATCHED AT TOP OF STAIRS IN 2 PLACES, 3 PALE PIECES OF HARDWOOD AT TOP OF STAIRS, IN KITCHEN AKO ONE IN CENTER OF LIVING ROOM.		
WINDOWS	SCREEN MISSING ON WINDOW TO LEFT OF PATIO DOOR	<u></u>	
GARDEN/PATIO DOORS			
NOTE;	SCREEN MISSING. NABLD SCRAPED, AND GLUE STOCK ON INSIDE OF DOOR		



THE COMPLEYED PRE-DELIVERY INSPECTION IS A FORMAL R. POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE *Purchasers or owners who intend to designate someone to conduct the authorizing the designate to sign this form on their behalf.	WARRANTY REGIDERTS	
Builder Representative	Purchaser	
Designate's Name(please print)	Designate's Signature	
i the homeowiter, confirm that all repair work listed has been completed	V	
	Purchaser	Date