

PDI Page 1 of 1 **TARION**

Vendor/Builder#

34234

Phone Res:

Robert Ryan Tuck and Jeff Cohen (647) 981-6384

Phone Bus : Closing Date : inspector:

2011-06-01

Enrollment#

Legal Address:

Project: Pian #: Lot / Phase #:

Municiaplity:

3002 / ESV

DLS[19]

Pratt Hunsen Group

Inspection Date: 29 May 2011

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition.

Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial aft changes and deletions As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- Bathtub sinks and toilets

- Bathroom excessories if provided
 Mirrors, counter tops and cabinelry
 Flooring (hardwood, viryl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace

WALLS

- Hor water heater, if provided (not rental)
 Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors including garage overhead doors, door locks

AND PAINT TOCCH UPR

- Faucets: Kitchen, bathroom, laundry room
 Exhaust fans (kitchen, bathrooms) if provided
 Electrical outlets and fixtures
 Gas fireplaces, incl. circulation fans, if provided
 Heat Recovery Ventilation system, if provided
- Heating system
- · Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

Also list here anything that can't be assessed because for example is dirty or inaccessible

GENERAL COMMENTS	
INSPECTION START TIME	INSPECTION STARTED ATIO: 10 ** PERCHASER WAS A NEW PHONE NUMBER -547-981-6384
NOTE:	UNIT KOT CLEANED. MINOR SANDING AND PAINT TOCCH U REQUIRED
MACTOD DEDDOOM	

MAIO POPPING OUT OF WINDOW FRRAME, TOP RIGHT HAND TRIM

SIDE

MAIN BATHROOM

HOLE IN MAIN BATH DOOR EXTERIOR. FOYER/HALL

COVER PLATES LOOSS IN SOME AREAS ELECTRICAL/LIGHTING CHIPPED CERAMIC NEAR FRONT ENTRY DOOR, GROUT DARK FLOORING

SPOT NEAR ENTRY TO BEDROOM 3. KITCHEN CEILING SAND AND PAINT MEAR LIGHT.

> RECEIVED MAY 3 0 2011

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL REPOSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE Verificators or owners who intend to designate someone to conduct the inathorizing the designate to sign this form on their behalf. Builder Representative		
Designate's Name(please print) I the homeowner, confirm that all repair work listed has been completed.	Designate's Signature	
	Purchaser	Date