

Bruto 3011

[3] Sydeham Wells - Unit 11

- missing hand cranks for all windows ✓

- missing all window screens ✓

- patio door doesn't lock ✓

- patio screen sticks ✓

- missing plate on light switch in hallway X

- cracked tile on floor in laundry room ✓

- missing tile around shower head ✓

- tile missing around bathtub faucet ✓

- toilet paper holder not attached in main bathroom ✓

- front door and lock sticks ✓