1033 95 GOODWIN DR. #5



BHC-01033

Pre-Delivery Inspection Form

OCT 0 6 2008

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any "substitutions" of items referred to in, or to be selected under, the Agreement of Purchase and Sale (APS), Please initial all changes and deletions, As a minimum

DAMAGED, INCOMPLETE OR MISSING OPERATING CONDITION Windows, side lights and other glazing. Window and door screens Windows, interior and exterior doors (including garage overhead · Bathtubs, sinks and toilets door). Door locks Bathroom accessories, it provided · Faucets: kitchen, bathroom, laundry room Mirrors, countertops and cabinetry Exhaust fans (kitchen, bathrooms), if provided Flooring (hardwood, vinyl, ceramic tiles, carpeting) Electrical outlets and fixtures · Interior finishes and trim carpentry Gas fireplaces, incl. circulation fans, if provided Furnace Heat Recovery Ventilation system, if provided Hot water heater, if provided (not a rental) Exterior finishes, driveways, walkways, decks and landscaping are Heating system Hot water heater, if provided (not a rental) complete Air conditioning system, if provided and if conditions permit

Item	# Room/Location	Description
1	FRONT DOOR	PAINT THE 100
2	FURNACE	FILES DE
3	MAIN WALLAND	COLLE DET HOT FIT
	The state of the s	THING THEY UPS ON WALL AND
4	1 AVOIDED DO	CCILING IS ROJEH, DOOR RUBS ON FLOOR
-/-	CONTROL TOO	PAINT TULY UPS FILTER DOET HOT FIT PAINT TOUCH UPS ON WALL AND CUTUNG IS ROUGH, DOOR RUBS ON FLOOR FRAN HOS FLUSY WITH CETUNG.
<u> </u>		
 		
$-\downarrow$		

Comments .