Lot 9029. N Dr. 93 UN. 3

Comments



Pre-Delivery Inspection Form

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any "substitutions" of items referred to in, or to be selected under, the Agreement of Purchase and Sale (APS), Please initial all changes and deletions, As a minimum check the following:

DAMAGED, INCOMPLETE OR MISSING **OPERATING CONDITION** · Windows, side lights and other glazing. Window and door screens · Windows, interior and exterior doors (including garage overhead · Bathtubs, sinks and toilets door). Door locks · Bathroom accessories, it provided · Faucets: kitchen, bathroom, laundry room • Exhaust fans (kitchen, bathrooms), if provided · Mirrors, countertops and cabinetry · Flooring (hardwood, vinyl, ceramic tiles, carpeting) · Electrical outlets and fixtures · Interior finishes and trim carpentry • Gas fireplaces, incl. circulation fans, if provided · Heat Recovery Ventilation system, if provided · Hot water heater, if provided (not a rental) Heating system • Exterior finishes, driveways, walkways, decks and landscaping are · Hot water heater, if provided (not a rental) complete · Air conditioning system, if provided and if conditions permit

Item #	Room/Location	Description
	MASTER BOOKS	MUNDOW WITH CRICLES NAIL POPIN
		LEDGE
2	RAILINGS	COMPLETE CLUAR COAT
3	KITCHEN	CABINETS 3 MISSING DOOKS
		SMALL CUIP IN FIRE CABINET UPPER
		RIGHT SIDE OF RANGE HOOD, TOP BLANCE
		FACE PLAKE BLOKON.
4	PATO DOOR	SCROWN DOED NOT SLIDE OR CLOSE
		PROPORLY, PATCY TRUM TO RIGHT SIDE OF ROLL
5	pan	PAREN MOLE ON AK.
6	STAIR WAL	CARPET AT TUP OF STAINI PATCY
7	GRAT ROOM	NAIL POP
8	LITCHN	BRUSPLASH TO BE INSTRUCTS # ZASFSA
		INSMO ZAS ABOI INSMI#1
		ZA5DB02
9	CARPET	NAILS IN FLOOD IN FRONT OF PATO DOWN
		ANO NOON KITCHEN
10	EXPONION	PAINI TIRIM.
<u> </u>		