



# PDI Page 1 of 1



Vendor/Builder # 34234  
Purchaser Name : Sharon Saint  
Phone Res : (705) 722-9936  
Phone Bus :  
Closing Date : 2012-07-09  
Inspector: Bruno Tidd

Enrollment # 1748626  
Legal Address: DLS(19)  
Project: Pratt Hansen Group  
Plan #:  
Lot / Phase #: 39105 / Building 39  
Municipality:

Inspection Date: 30 Jun 2012

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition.  
Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS).  
Please initial all changes and deletions. As a minimum, check the following:

## DAMAGED, INCOMPLETE OR MISSING

• Windows, side lights and other glazing, Window and door screens

• Bath tub sinks and toilets  
• Bathroom accessories if provided  
• Mirrors, counter tops and cabinetry  
• Flooring (hardwood, vinyl, ceramic tiles, carpeting)  
• Interior finished and trim carpentry  
• Furnace  
• Hot water heater, if provided (not rental)  
• Exterior finished, driveways, walkways, decks and landscaping

## OPERATING CONDITION

• Windows, interior and exterior doors including garage overhead doors, door locks  
• Faucets: Kitchen, bathroom, laundry room  
• Exhaust fans (kitchen, bathrooms) if provided  
• Electrical outlets and fixtures  
• Gas fireplaces, incl. circulation fans, if provided  
• Heat Recovery Ventilation system, if provided  
• Heating system  
• Hot water heater, if provided (not rental)  
• Air conditioning system, if provided and if conditions permit

Also list here anything that can't be assessed because for example is dirty or inaccessible.

## GENERAL COMMENTS

INSPECTION START TIME INSPECTION STARTED AT 10:AM  
NOTE: TOUCH UPS REQUIRED THROUGH OUT AS INDICATED. NO HOT WATER.

## MAIN BATHROOM


VANITY CABINETS CHIPPED GABLE END NEXT TO TOILET CHIPPED AT BASE FRONT NEAR KICK PLATE,

## KITCHEN

CABINETS LOWER CABINET TO LEFT OF STOVE HAS NO SHELF.

## EXTERIOR

DECK 2 SMALL BUBBLES IN DECK ON EITHER SIDE OF PATIO DOOR.



THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS

\* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.

Builder Representative

Purchaser

Designate's Name (please print)

Designate's Signature

I the homeowner, confirm that all repair work listed has been completed

Purchaser

Date