rake inii



PDĮ Page 1 of 1



Vendor/Builder#

34234 Owen Rawn and Donna Rawn

Purchaser Name: Phone Res:

(705) 733-3406

Phone Bus : Closing Date : Inspector:

2011-12-15

Bruno Tidd

Enrollment# Legal Address:

Project:

Plan #:

DLS[19] Pratt Hans

Municiaplity:

39308 / Building39

Inspection Date: <u>17 Jan 2012</u>

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition.

Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS).

Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- Bathlub sinks and toilets

- Bathroom accessories if provided
 Mirrors, counter tops and cabinetry
 Flooring (hardwood, vinyl, ceramic tiles, carpeting)
 Interior finished and trim carpentry

Hot water heater, if provided (not rental)
 Exterior finished, driveways, walkways, decks and landscaping


OPERATING CONDITION

- Windows, interior and exterior doors including garage overhead doors, door
- Faucets: Kitchen, bathroom, faundry mom
 Exhaust fans (kitchen, bathrooms) if provided

- Electrical outlets and fixtures
 Gas Irreplaces, including family fixed the Recovery Ventilation system, if provided Heating system
- · Hot water heater, if provided (not rental)
- · Air conditioning system, if provided and if conditions permit

Also list here anything that can't be assessed because for example is dirty or inaccessible.

GENERAL COMMENTS		
INSPECTION START TIME NOTE:	INSPECTION STARTED AT 5:10 P.M. CRANKS AND SCREENS FOR WINDOWS NOT INSTALLED. TOUCH UPS REQUIRED THROUGH OUT AS INDICATED. COVER PLATES FOR CABLE OUTLETS NOT INSTALLED.	
MASTER ENSUITE BATH		
VANITY CABINETS	KICK PLATE UNDER VANITY AND PATCH MARK NOT PAINTED.	
LIVING ROOM		
WALLS	PAINT STREAMS ON CEILING.	
KITCHEN		
WALIS	BACKSPLASH TILE BROKEN AT 2 OF THE ELECTRICAL OULETS. BACKSPLASH NOT GROUTED AT BASE OF WALL BEHIND SINK AND TO RIGHT OF STOVE.	
CABINETS	CHIPFED INTERIORPANEL TO RIGHT OF RANGE HOOD.	



THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS * Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder author/sing the designate to sign this form on their behalf. Builder Representative				
Designate's Name(please print) I the homeowner, confirm that all repair work listed has been completed	Designate's Signature			
	Purchaser	Date		

31001-PDJF-01,01