

Pratt HOMES		PDI Page 1 of 1		TARION	
Vendor/Builder #	34234	Enrollment #	1748655		
Purchaser Name :	Mark Boryniak	Legal Address:	DLS[19]		
Phone Res :	(705) 722-6492	Project:	Pratt Hansen Group		
Phone Bus :	-	Plan #:			
Closing Date :	2012-02-28	Lot / Phase #:	39310 / Building39		
Inspector:	Bruno Todd	Municipality:			
Inspection Date: 22 Feb 2012					

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens

- Bathtub sinks and toilets
- Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

Also list here anything that can't be assessed because for example is dirty or inaccessible.

OPERATING CONDITION

- Windows, interior and exterior doors including garage overhead doors, door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- Electrical outlets and fixtures
- Gas fireplaces, incl. circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

GENERAL COMMENTS

INSPECTION START TIME INSPECTION STARTED AT 5:35

NOTE:

TOUCH UPS REQUIRED THROUGH OUT AS INDICATED SCREENS AND CRANKS MISSING FROM WINDOWS. SHOOTERS CROOKED AND HANDLES WERE NOT SUPPOSED TO BE ON INSIDE

KITCHEN


CABINETS

UPPER TO LEFT OF STOVE OPENING SCRAPES WHEN OPENED. LOWER LEFT DOOR UNDER SINK SCRAPES WHEN OPENED. CHIPPED AND MINOR SCRAPES WHERE MARKED. LOWER CABINET RIGHT DOOR TO RIGHT OF FRIDGE SCRAPES WHEN OPENED.

EXTERIOR

NOTE:

PAINT SPLATTERS ON STUCCO TO LEFT OF PATIO DOORS.



THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS
 * Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.

Builder Representative

Purchaser

Designate's Name (please print)

Designate's Signature

I the homeowner, confirm that all repair work listed has been completed

Purchaser

Date