

PDI Page 1 of 1



Vendor/Builder#

Purchaser Name: Phone Res:

34234 Anthonia Olufbyikemi (705) 735-3129 (705) 792-7818

Phone Bus: Closing Date: Inspector:

Bruno Tidd

Enrollment# Legal Address: Project;

748657 Pratt Hansen Group

Plan #: Lot / Phase #: Municiaplity;

39312 / Building39

Inspection Date: 13 Mar 2012

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition.

Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

Windows, side lights and other glazing. Window and door screens

- · Bathtub sinks and toilets
- Bathroom accessories if provided
 Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tites, carpeting)
 Interior finished and trim carpentry

Hot water heater, if provided (not rental)
 Exterior finished, driveways, walkways, decks and landscaping
 Also list here anything that can't be essessed because for example.


OPERATING CONDITION

- Windows, interior and exterior doors including garage overhead doors, door locks
- · Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
 Electrical outlets and fixtures
- Gas fireplaces, inclairculation fans, if provided
 Heat Recovery Ventilation system, if provided

- Heating system
 Hot water heater, if provided (not rental)
- · Air conditioning system, if provided and if conditions permit

	be assessed occasion for example is direy in maccessible.	
GENERAL COMMENTS		
INSPECTION START TIME	INSPECTION STARTED AT 5:30 P.M.	
NOTE:	TOUCH UPS REQUIRED THROUGH OUT AS INDICATED	
MASTER ENSUTTE BATH		
TRIM	DOOR STOPPER NOT INSTALLED	
BEDROOM #2		
ELECTRICAL/LIGHTING	COVER PLATES MISSING OVER TWO OUTLETS.	
DINING ROOM		
WINDOWS	CASING CRANK DOES NOT FIT ON UNIT	
KITCHEN		
CABINETS	BACK PANEL OF PANTRY CRACKED IN 2 PLACES, CROWN MOULDING OVER FRIDGE OPENING JOINT IS SEPERATING.	
EXTERIOR		
DECK	STUCCO CUIDDED AM DOOD DVINDAMOR	

PATO DOOR DIFFICULT TO LOVE



THE COMPLETED PRE-DBLIVERY INSPECTION IS A FORMAL RE POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE V * Purchasers or owners who intend to designate someone to conduct the i	WARRANTY REQUESTS	
authorizing the designage to sign this form on their behalf.	Dn_{-}	aminor hy no the version rounder
131(0)	D-Gunmotein	
Birlider Representative	Purchaser	
		
Designate's Name(please print)	Designate's Signature	
I the homeowner, confirm that all repair work fisted has been completed		
	Purchaser	Date