

Consider This as The PDI

Mr. George Bennett 41-107 Ferndale Dr S.
51M-959 L4N 5T6

PRE DELIVERY INSPECTION JUNE 25TH 9.30 p.m.

Kitchen - Backsplash to be installed

General Comment - Unit needs to be cleaned

Kitchen - upper cabinets over stove do not close properly - upper to left of stove wobbles

Washroom - pinhole in caulking and slight mould in right rear corner

- caps missing on both sides of Toilet secure bolts

Living Room - corner bead visible on hall wall adjacent to kitchen peninsula.

BN Greid June 25, 2013

x JB Bennett June 25, 2013

PDI - 1748676

Closes July 4/13

