

## PDI Page 1 of 1



Vendor/Builder# Purchaser Name :

34234 Dianna Klatt

Phone Res: Phone Bas: (905) 602-4226

Clasing Date: Inspector:

2011-12-15 Bruno Tidd

Enrollment#

Legal Address; Project:

M48681

Plan#:

DLS[19] Pratt Hansen Group

Lot / Phase #: MuniciapEty:

4H12/Building41

Inspection Date: 10 Dec 2011

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition.

Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

- DAMAGED, INCOMPLETE OR MISSING

  Windows, side lights and other glazing. Window and door screens

- Bathrub sinks and toitets
   Bathroom accessories if provided
   Mirrors, counter tops and cabinetry
   Plooring (hardwood, vinyl, ceramic tiles, carpeting)
   Interior finished and trim carpentry


· Hot water heater, if provided (not rental)
· Exterior finished, driveways, walkways, decks and landscaping

- OPERATING CONDITION

   Windows, interior and exterior doors including garage overhead doors, door Windows, interior and exterior doors including a locks
  Faucets: Kitchen, bathroom, feundry room
  Exhaust fans (kitchen, bathrooms) if provided
  Electrical outlets and fixtures
  Gas fireplaces, incl. circulation fans, if provided
  Heat Recovery Ventilation system, if provided
  Heating system
  Hot water healer, if provided (not rental)

- · Hot water heater, if provided (not remail)
- · Air conditioning system, if provided and if conditions permit

Also list here anything that can't ! GENERAL COMMENTS	be assessed because for example is dirty or inaccessible.		
INSPECTION START TIME	INSPECTION STARTED AT 4:00 P.M.		
NOTE:	TOUCH UPS REQUIRED THROUGH OUT AS INDICATED. WSCREENS AND CRANKS MISSING FROM WINDOWS.		
MASTER ENSUITE BATH			
SINK	SINK NOT SECURE		
ELECTRICAL/LIGHTING	COVER PLATE MISSING FOR FAN OPENING.	<u></u>	<del></del>
MAIN BATHROOM			
-	NO HANDLE ON GLASS SHOWER DOOR.		
SINK	NOT SECORED	<del></del>	<del></del>
FOYER/HALL			
WALLS	COVER PLATE FOR SPRINKLER HEAD MISSING OVER DOOR.		
KTCHEN			
COUNTERTOPS	SCRATCHED TO LEFT OF TOVE.		



THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS  * Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builden authorizing the designate to sign this form on their behalf.    D   D   D   D   D   D   D   D   D			
Designate's Name(please print) I the homeowner, confirm that all repair work listed has been completed	Designate's Signature  Purchaser	 Date	

10.10-7IIQ9-1001E