

## PDI Page I of 1



Vendor/Bulkler#

Doug Potter and Betty Potter (705) 726-4634 Purchaser Name:

Phone Res : Phone Bus:

Closing Date: Inspector:

2012-04-24 Bruno Tidd Egrollment#

Legal Address: Project; Plan#;

DLS[19] Pratt Hansen Group

Lot / Phase #: Municiapility:

41307 / Building41

Inspection Date: 18 Apr 2012 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition.

Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS).

Please initial all changes and deletions As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

Windows, side lights and other glazing. Window and door screens

- · Bathtub sinks and toilets
- Bathroom accessories if provided
- · Marrors, counter tops and cabinetry · Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and frim carpentry
   Furnace


- Hot water heater, if provided (not rental)
   Exterior finished, drivewaya, walkways, decks and landscaping Also list here envising that can't be assessed because for example.

OPERATING CONDITION

- Windows, interior and exterior doors including garage overhead doors, door

- Faucets: Kitchen, bathroom, laundry room
  Exhaust fans (kitchen, bathrooms) if provided
  Electrical outlets and fixtures
  Gas fireplaces, incl. circulation fans, if provided
  Heat Recovery Ventilation system, if provided
- Heating system
   Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

| cao nat nese miyenne, mat car | it be assessed occarse for example is diffy of inaccessible.  |             |                  |
|-------------------------------|---|-------------|------------------|
| GENERAL COMMENTS              |   |             |                  |
| INSPECTION START TIM<br>NOTE: | E INSPECTION STARTED AT 1:00 P.M. TOUCH UPS REQUIRED THROUGH OUT AS INDICATED. CROWN MOULDING SEAMS TO BE DAPPED. | -           | <del>-1121</del> |
| LIVING ROOM                   |   |             |                  |
| FLOORING                      | HARDWOOD SCRATCHED BADLY IN FRONT OF ENTRY CLOSET DOOR.   |             |                  |
| GARDEN/PATIO DOORS            |   | <del></del> |                  |
| NOTE:                         | SCREEN HAS NOLES.   |             |                  |
| KITCHEN                       |   |             |                  |
| COUNTERTOPS                   | GRANITE SEAMS ARE UNEVEN ON BOTH SIDES, COUNTERTOR COULD BE RE CLEANED.   |             |                  |



| THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAUR POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE Purchasers or owners who intend to designate someone to conduct the authorizing the designate to figurithis form on their behalf. | WARRANTY REQUESTS     |      |
|---|-----------------------|------|
| Builder Representative  | Parchaser             |      |
| Designate's Name(please print)  | Designate's Signature |      |
| I the homeowner, confirm that all repair work listed has been completed   |                       |      |
|   |                       |      |
| <u>.                                    </u>  | Purchaser             | Date |