
LOT 100 (MWI) ST'





Pre-Delivery Inspection Form

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any "substitutions" of items referred to in, or to be selected under, the Agreement of Purchase and Sale (APS), Please initial all changes and deletions, As a minimum check the following:

DAMAGED, INCOMPLETE OR MISSING	OPERATING CONDITION
 Windows, side lights and other glazing. Window and door screens Bathtubs, sinks and toilets Bathroom accessories, it provided Mirrors, countertops and cabinetry Flooring (hardwood, vinyl, ceramic tiles, carpeting) Interior finishes and trim carpentry Furnace Hot water heater, if provided (not a rental) Exterior finishes, driveways, walkways, decks and landscaping are complete 	Windows, interior and exterior doors (including garage overhead door). Door locks Faucets: kitchen, bathroom, laundry room Exhaust fans (kitchen, bathrooms), if provided Electrical outlets and fixtures Gas fireplaces, incl. circulation fans, if provided Heat Recovery Ventilation system, if provided Heating system Hot water heater, if provided (not a rental) Air conditioning system, if provided and if conditions permit

DOUBLAY TRUMBUE Description Item # | Room/Location GRADING, SOD PAVED OF WENDY PAINTING, EXPRIM RMUNT, RETMINING WALL. MAN BOOR - GAP 10 TOP. CUGONIER CONCERNED ABOUT FUNCTION AND EXTECLOR GARAGE STATURES TO 24 MOT FINISHED FLOOR VENT DESKY KIT /THROUBY OF HOME BAR @ TOP OF FROM POOR HANDE BEDROOM KZ 9 VERLY TOP STEP W 2MD 871711S TO 2110 10 AIR VIAPPER NOT GUNCTIONING ON HOOD FAIN 1400*0 149*11/ MISSIMF SHFLF FITTER WERE NOT ACCESSIBLE