
rol Son Bly May

ONHW-PDIF-01.01





**Pre-Delivery Inspection Form** 

Please list below any damaged, incomplete, or missing items and anything that is not in good operating of um

DAMAGED, INCOM	IPLETE OR MISSING	OPERATING CONDITION
<ul> <li>Bathroom accessories, it pro</li> <li>Mirrors, countertops and cab</li> <li>Flooring (hardwood, vinyl, ce</li> <li>interior finishes and trim carp</li> <li>Furnace</li> <li>Hot water heater, if provided (</li> </ul>	netry amic tiles, carpeting) entry	<ul> <li>Windows, interior and exterior doors (including garage overhead door). Door locks</li> <li>Faucets: kitchen, bathroom, laundry room</li> <li>Exhaust fans (kitchen, bathrooms), if provided</li> <li>Electrical outlets and fixtures</li> <li>Gas fireplaces, incl. circulation fans, if provided</li> <li>Heat Recovery Ventilation system, if provided</li> <li>Heating system</li> <li>Hot water heater, if provided (not a rental)</li> <li>Air conditioning system, if provided and if conditions permit</li> </ul>
noments <u>AUGUAS</u> 70.	umore I ang m	<i></i>
m# Room/Location	Description	
MORTOR	PAM ON TRUM A	NE KARAGE MANDOR
EXPERTOR	DIWNSBUT WAY	AF INAME OF COME

MINDER MISSING MATIN BATH TOLLES RUNNING UNEW CLOSES NO SHELLES HOSE BIBB CUSTOMER NOT HAPPY WITH LOCATION BUN 1240 NEEDED GREAT ROOM & BULL HEAD REPAIR NOT COMPLETED CETUNG STIPPLE NEEDED.



Item#	Room/Location	Assessed, because for example it is obscured from view or inaccessible.  Description
	ROOF	COULD NOT TAISPET
2_	ATTIC	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
3	LANW	(I
	<u> </u>	
<u> </u>		
_	· <u> </u>	<del></del>
	-	
_	· <u> </u>	·
_ <del>_</del> .	<del>-</del>	
	<del> </del> -	
_ <del>_</del>	<del>-</del>	
<u> </u>	<del>-</del>	
<del></del>	<u> </u>	
<del></del> .	<del>_</del>	
	<del>_</del>	
	_	
	der and Home Addres	
Date of 1	Possession: Mn.O.C	1 15,2010 Vendor/Builder Reference # 34234  7 m. 892 Municipality INNISTIC
- 1	Sell.	Vendor/Builder Reference # 34234
Lot 🗷 t	Plan # <u></u>	1m. 8/2 Municipality LNNISFIC
Project N	Vame <u> </u>	Solk by the BROOK
Home/Ci	ivic Address 140	Spek by the BROOK  RAWKIN WAY
(please p	rint)	
Vendor/E	Builder Name PF	ATT HANSEN GROUP INC.
1	10.	
LOUG Parrosa	RIRUME	SLE
Represen	itative's Name (please	e print) Representative's Menature
	·	
is section s	should be completed :	and signed by all persons who are shown as purchasers on the APS for the home, or
	and III a constitucito	a contract (and/or by their designate*).
I have ins	pected my new home	and I agree that the descriptions of the items listed on this form are accurate.
	ı	$I \cap I \cap I$
Burchage	W / L L P	no Re Us lan/Ill
Purchasei	rs Name (picase prin	Purchaser's Signature
		1/
Purchasea	's Name (please prin	Prophagovia Silvers
	. Virginia bani	Purchaser's Signature
Designate	's" Name (please pri	nt) Designate's" Signature
MY	29, 72/	)
Date		

\*\*Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.

THE COMPLETED PRE-DELIVERY INSPECTION FORM IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION. IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY SERVICE REQUESTS. 2010 \_\_ Unit Enrolment # \_