
Lot 98 (mws) 2166 Ne Vils





Pre-Delivery Inspection Form

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any "substitutions" of items referred to in, or to be selected under, the Agreement of Purchase and Sale (APS), Please initial all changes and deletions, As a minimum check the following:

DAMAGED, INCOMPLETE OR MISSING	OPERATING CONDITION	
 Windows, side lights and other glazing. Window and door screens Bathtubs, sinks and toilets Bathroom accessories, it provided Mirrors, countertops and cabinetry Flooring (hardwood, vinyl, ceramic tiles, carpeting) Interior finishes and trim carpentry Furnace Hot water heater, if provided (not a rental) Exterior finishes, driveways, walkways, decks and landscaping are complete 	Windows, interior and exterior doors (including garage overhead door). Door locks Faucets: kitchen, bathroom, laundry room Exhaust fans (kitchen, bathrooms), if provided Electrical outlets and fixtures Gas fireplaces, incl. circulation fans, if provided Heat Recovery Ventilation system, if provided Heating system Hot water heater, if provided (not a rental) Air conditioning system, if provided and if conditions permit	
Comments DOUBLAS TRUBLE //OULAL/		

Item #	Room/Location	Description
	EXTERIOR	MORTAL TOUGH-UPS INCOMPLETED,
		MOSTAL TOUGH-CPS INCOMPLETED,
2	EXTERIUR	CURRENT GRADING ALUNING WATER TO
	·	PROTECTIVE CORTING TO BE RENOVED FROM SUDERS
3	INTERIOR	PROTEITUE COMING-TO BE RENOVED FROM
	,	SUPER
4	INTERIOR/MAIN	DATH-FLOR VENT DESN'T FOT FULL ME- FLOR VENT DOESN'T FOT FLUSH, DAMPNESS/NOUSTARE APPARENT IN PLOCES
	Ens	WE- From VENT BOESN + KIT FLUSH,
5	BOSEMENT,	OMPNESS/NOWTHE APPARENT IN HORK
+		
_		
		05/04 00 / - 1/2/04/17