

PDI Page 1 of f



Page I of I

Vendor/Balkier#

Purchaser Name : Phone Res :

Savy Kalivoda (705) 717-9329

Phone Bus: Closing Date:

2013-03-14 Brano Tidd

Enrollment# Legal Address: Project: Plan #: Lot / Phase #:

Municlaplity:

DLS[19] H Hansen Development Inc

SWD-0003871

Inspection Date: 13 Mar 2013

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition.

Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS).

Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

Windows, side lights and other glazing. Window and door screens

OPERATING CONDITION

Windows, interior and exterior doors:

- Bathtub sinks and toilets
 Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
 Flooring (hardwood, vinyl, ceramic tiles, carpeting)
 Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
 Exterior finished, driveways, walkways, decks and landscaping
- Windows, interior and exterior doors including garage overhead doors, door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
 Electrical outlets and fixtures

- Gas fireplaces, incl.circulation funs, if provided
 Heat Recovery Ventilation system, if provided
 Heating system
 Hot water heater, if provided (not rental)
 Air conditioning system, if provided and if conditions permit

Also list here anything that can't be assessed because for example is dirty or inaccessible.

GENERAL COMMENTS	<u> </u>		
INSPECTION START TIME NOTE:	INSPECTION STARTED AT 8:12 PAINT TOUCH OPS, ALL MIRRORS , ALL CLOSET DOORS , ALL SHELVES TO BE INSTALLED	_	
MASTER ENSUITE BATH			
	DOORS ON SHOWER ARE MISSING.		
MAIN BATHROOM			
TUB	CAULK AROUND FLOOR AND TUB AND REMOVE PLASTIC		
STAIRS			
RAII,ING	ROUGH FINISH		
KITCHEN			
-	WRONG COLOUR CABINETS INSTALLED (WHITE WERE INSTALLED) SHOULD SE VERMOUNT NATURAL MAPLE DISHWASHER SPACE IS NEEDED TO FIT DISHWASHER COT IN PARDWOOD FLOOR IN FRONT OF CABINETS.		
STAIRS TO BASEMENT	· · · · · · · · · · · · · · · · · · ·	_	
2 52215	-CRRENED		
RAILING	MISSING		
VINISHED BASEMENT			-
NOTE:	COORS TO BE INSTALLED IN FURNACE AREA AND HOT WATER AREA. HARDWEAR ON ALL DOORS TO BE INSTALLED.		
BASEMENT			
NOTE:	BASEMENT TOILET TO BE INSTALLED		
EXTERIOR		- <u>-</u>	
NOTE:	OUTSIDE WATER SOURCE TAD MISSING		

POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE	BCORD OF THE HOME'S CONDITION WARRANTY REQUESTS	N DEFORE THE PURCHASER TAKES
" Purchasers or owners who intend to designate someons to conduct the	PDI in their place should ensure they re-	wide written authority to the pender/hullder
authorizing the designate to sign this form on their behalf.	• .	the second section of the second sections and the
Steller fr.	folk	
Builder Representative	Purchasor	RECEIVED
		MAR 2 1 2013
Designate's Name(please print)	Designate's Signature	1.82-0m2
I the homeowner, confirm that all repair work listed has been completed		-2-25
	Purchaser	Date

31001-PDIF-01,01