

Pratt Hansen Group Customer Service Phone: (705) 792-3883

Work Order

Address:

39 Coulter St Unit 26 - Barrie

Location:

Sunnidale Vistas - Phase: SUN - Lot: 1026

Today's Date:

15Jul10

Contact Name(s):

Bruno Di Domenico and Betti Di Domenico

Contact Phone No.: Res: (705) 252-7115 Bus: Bus2: Cell: (416) 458-09

Company:

Decora Window and Door Systems

Attention:

Diana

Telephone: Fax:

(905) 660-9212

(905) 660-9788

Deficiency Number	Issue	Appt.	Notes
i c i n re	SARDENPATIO DOCKS- Scratched and dented at base on both sides. **The owners report that your service man told them this was too big a job & that they should learn to live with the damage. We do not agree. The interior bottom vinyl track las impact damage. Please eplace the damaged part. et us know what the charge & we will issue a PO.**	Date/Time	

Date Completed: 19-11-2010

Homeowner Sign

riease schedule service to complete the work described above within two weeks of receipt of this work Order. It is your responsibility to book your own appointment unless we have included appointment details on this form.

Your Service Person must ask the homeowner to sign this form when the work has been completed. If the owner is not available to sign this Work Order, the person who completes the work should sign and date the form. Fax the completed Work Order to us at 705-735-6991.

In the event that you do not complete this service work within 14 days, Pratt Homes reserves the right to carry out the repairs on your palpalf and the labour and material costs may be billed back to you plus a

This fax was sent with GFLFAXmaker fax server. For more information, visit: http://www.ofi.com