From: Pratt Homes

To: Ramona Gross

Page: 1/2

Date: 1/27/2011 1:16:00 PM

FAX TRANSMISSION

To: Pratt Hansen Group Inc.

From: Pratt Homes

Subject: Work order Re: Sunnidale Vistas - SUN - 1030 - Dominion Sheet Metal and Roofing

Message: This workorder is still outstanding. If completed please fax completed

workorder.lf not please schedule repair asap. & advise Pratt Service Dept. we

are tracking incomplete w/orders. Thank you Ramona

From: Pratt Homes To: Ramona Gross Page: 2/2 Date: 1/27/2011 1:16:00 PM



Pratt Hansen Group Customer Service Phone: (705) 792-3883

Fax: (705) 792-3893

Work Order

Address: 39 Coulter St Unit 30 - Barrie

Location: Sunnidale Vistas - Phase: SUN - Lot: 1030

Today's Date: 27Jan11

Contact Name(s): Marzanna Warczak

Contact Phone No.: Res: privatenumber Bus: Bus2: Cell: Company: Dominion Sheet Metal and Roofing

Attention:

Telephone: (416) 789-0601 **Fax**: (647) 438-9165

Please Complete the following items:

Deficiency Number	Issue	Appt. Date/Time	Notes
2434	Exterior- on the balcony roof fascia is damaged on the corner, visible from ground		

Date Completed:	Homeowner Signature:
-----------------	----------------------

Please schedule service to complete the work described above within two weeks of receipt of this Work Order. It is your responsibility to book your own appointment unless we have included appointment details on this form.

Your Service Person must ask the homeowner to sign this form when the work has been completed. If the owner is not available to sign this Work Order, the person who completes the work should sign and date the form. Fax the completed Work Order to us at 705-735-6991.

In the event that you do not complete this service work within 14 days, Pratt Homes reserves the right to carry out the repairs on your behalf and the labour and material costs may be billed back to you plus a 15% administrative fee.