



**Pratt Hansen Group**  
**Customer Service**  
**Phone: (705) 792-3883**  
**Fax: (705) 792-3893**

## Work Order

**Address:** 41 Coulter St Unit 21 - Barrie  
**Location:** Sunnisdale Vistas - Phase: SUN - Lot: 2021  
**Today's Date:** 13Dec10  
**Contact Name(s):** Randy J Mastaler  
**Contact Phone No.:** Res: (705) 790-0303 Bus: (705) 790-0303 Bus2: (705) 689-0537 Cell:  
**Company:** Can-Barr Mechanical  
**Attention:**  
**Telephone:** (705) 728-7617  
**Fax:** (705) 728-3271

**Please Complete the following items:**

Deficiency Number	Issue		Appt. Date/Time	Notes
4309	Main Bathroom- leakcoming from ceiling in hte corner 2' down the wall and drywall has bubbled up			
4314	Main Bathroom- when toilet is flushed bathtub drain gurgles, says drain vent might be plugged			

Date Completed: \_\_\_\_\_

Homeowner Signature: \_\_\_\_\_

Please schedule service to complete the work described above within two weeks of receipt of this Work Order. It is your responsibility to book your own appointment unless we have included appointment details on this form.

Your Service Person must ask the homeowner to sign this form when the work has been completed. If the owner is not available to sign this Work Order, the person who completes the work should sign and date the form. Fax the completed Work Order to us at 705-735-6991.

In the event that you do not complete this service work within 14 days, Pratt Homes reserves the right to carry out the repairs on your behalf and the labour and material costs may be billed back to you plus a 15% administrative fee.