LOT 5012 SWAN ST



WPI-5012

NOV 2 4 2008

Pre-Delivery Inspection Form

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any "substitutions" of items referred to in, or to be selected under, the Agreement of Purchase and Sale (APS), Please initial all changes and deletions, As a minimum check the following:

DAMAGED, INCOMPLETE OR MISSING	OPERATING CONDITION
 Windows, side lights and other glazing. Window and door screens Bathtubs, sinks and toilets Bathroom accessories, it provided Mirrors, countertops and cabinetry Flooring (hardwood, vinyl, ceramic tiles, carpeting) Interior finishes and trim carpentry Furnace Hot water heater, if provided (not a rental) Exterior finishes, driveways, walkways, decks and landscaping are complete 	Windows, interior and exterior doors (including garage overhead door). Door locks Faucets: kitchen, bathroom, laundry room Exhaust fans (kitchen, bathrooms), if provided Electrical outlets and fixtures Gas fireplaces, incl. circulation fans, if provided Heat Recovery Ventilation system, if provided Heating system Hot water heater, if provided (not a rental) Air conditioning system, if provided and if conditions permit
omments DOVBIAS TOUMBUTS. Jungle	1.

EXTERIOR CAVILING NEEDED AROUND BARBEDOOK AINTIMS MEDED ON FRONT WON CASING MERIOR , MOUN NOT CUTAN BASEMENT CLEMNOTHIS WHEN LEAK BASEMENT EVRNITA NO LAGGE / BRAND

Date 1001111923100 # 5012

Unit Enrolment # 1600 3 38