Lot 5060 ST. 1981 SWAN



## **Pre-Delivery Inspection Form**

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any "substitutions" of items referred to in, or to be selected under, the Agreement of Purchase and Sale (APS), Please initial all changes and deletions, As a minimum check the following:

## DAMAGED, INCOMPLETE OR MISSING **OPERATING CONDITION** Windows, side lights and other glazing. Window and door screens · Windows, interior and exterior doors (including garage overhead · Bathtubs, sinks and toilets door). Door locks · Bathroom accessories, it provided · Faucets: kitchen, bathroom, laundry room · Mirrors, countertops and cabinetry · Exhaust fans (kitchen, bathrooms), if provided · Flooring (hardwood, vinyl, ceramic tiles, carpeting) · Electrical outlets and fixtures · Interior finishes and trim carpentry · Gas fireplaces, incl. circulation fans, if provided Furnace • Heat Recovery Ventilation system, if provided · Hot water heater, if provided (not a rental) Heating system • Exterior finishes, driveways, walkways, decks and landscaping are · Hot water heater, if provided (not a rental) · Air conditioning system, if provided and if conditions permit

Commen	is PADUIS PRANTI	766.	H MARGER I
Item #	Room/Location	Descripti	tion
	DUCH-UPS INAT	um)	TOUCH-UPS THROUGH -ON
		_	
	<u></u>		
		· · · · · · · · · · · · · · · · · · ·	