

Zancor Homes (Innisfil) Ltd.

Phone: (905) 738-7010 **Warranty Services**

Fax: (905) 738-5948

Work Order

Address: Closing Date: 1534 Angus St. Innisfil, Ontario 17Dec20

Location: Belle Aire Shores - Phase: 1 - Lot: 9

Today's Date: 16Jun21

Contact(s):

Christopher, Joe Soares - Cell: (416) 476-3076 Diana, Marie Schebri - Home: (416) 476-3076 dianaschemb@gmail.com

Email:

Company: Zancor - Innisfil Warranty Service

Attention:

Telephone:

Fax:

Please Complete the following items:

		_	
142702	142700	142694	DAI
30-Day	30-Day	30-Day Seasonal	Туре
Other- General- Entire Main Floor has numerous scratches on the hardwood and	Stairs- General- Bow in the wall at the landing on the way to the second floorAS PER INSPECT TOLERNACE OF BOW IN RIGHT WALL (BACKING ON TO LAUNDRY)	Other- General- MUDROOMExterior Metal Door has visible dentsAS PER INSPECTION, FIX DENTS AT GMD (REPORTED BY H/O VIA EMAIL ON DEC 19)	Issue
		- 9	
16Jun21 /am	16Jun21 /am	16Jun21 /am	Appt. Date/Time
			Notes

142752	142745	142739	142717	142716	
30-Day	30-Day	30-Day	30-Day	30-Day	
Exterior- General- Water Leakage at exterior sliding doorsAS PER INSPECTION, LOOKS LIKE SNOW JUST	Other- General- Loose connections causing floor squeaks on the entire second floorAS PER INSPECTION. ROUMEN TO INSPECT AND REPORT BACK	Bedroom 3- General- Bedroom 3 Wall Damage beside closetAS PER INSPECTION, COMPLETE DRYWALL REPAIR AND PAINT	Shared Bathroom-General- Twin Bath Wall Damage beside tubAS PER INSPECTION, SKIM DRYWALL TO LEFT OF TUB AND PAINT	Master Ensuite- General- Trim looks to be cut too short and filled with a messy bead of caulkingAS PER INSPECTION, REDAP BASEBOARD TO KICK	were never cleaned. Paint is stuck in the grooves of some of the hardwoodAS PER INSPECTION, MINOR HARDWOOD TOUCH UPS AND CLEAN PAINT FROM HARDWOOD
16Jun21 /am	16Jun21 /am	16Jun21 /am	16Jun21 /am	16Jun21 /am	

14	1		
144715	142765	142753	
30-Day	30-Day Seasonal	30-Day	
Shared Bathroom-General- Unacceptable creaks in Bedroom 3 Ensuite TubAS PER INSPECTION, NO CREAK HEARD (reported on June 1, tub creak can now be heard)	Other- General- While powerwashing took place to clean the brick, all kinds of debris was left on the rooftop and never cleanedAS PER INSPECTION. CLEAN LOWER ROOF, SPRING/SUMMER 2021	Exterior- General- Extremely dirty windows - cleaning requiredAS PER INSPECTION, WILL RE-VISIT ONCE UNITRI HAS COMPLETED THE BRICK TINTING	MELTING BUT ROUMEN WILL RE- INSPECT
Ψ			
16Jun21 /am	16Jun21 /am	16Jun21 /am	
Arrival 8am			

Date Completed:

Date Completed:

has been completed in a workman like manner.

Trade &/or Service Tech

Signature:

Print Name:

adhere to the appointment you have scheduled. Your service representative must have this form appointment time or date appear (below) on this form, it is your responsibility to arrange and Please schedule your Service Department to complete work on the above Lot. Should no

signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.