

## NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

Service Date: Aug 18, 2021

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6 TEL (905) 672-1233 FAX (905) 672-1076

WO # W140269

		1	));;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;	7	: 1 : 2 : 2 : 2 : 2 : 2 : 2 : 2 : 2 : 2
Priority: Normal		Status:	OCHECOLED.	200	ZEERAGED
BUILDER	11 11 11 11				
Customer: 611383		City:	WASAGA BEACH	ed:	Jul 27, 2021
Name: ZANCOR WASAGA TOWNS	TOWNS	Service Phone(s):	i de la companya de l	Time:	·,2
Service Fax:		Site Phone:			D362309-1
Site Fax:		Lot#:	BLK134-3	Phase:	
RESIDENT INFORMATION					
Home Owner Name: SUCHARIT	SUCHARITA CHANDRA	Address:	54 brianca	a cres.	
	75	Work Phone(s):	1e(s):		
Cell Phone(s): 647-226-7799	99	Email(s):			
LINKED ORDER INFORMATION	×				
Customer: 611383 ZANCOR WASAGA TOWNS	ASAGA: TOWNS		Lot #: BLK134-3	3	
Model: TH-4			Phase:		
SERVICE INSTRUCTIONS		Mor.	The state of the s		
FRONT DOOR SLAB HAS A SMALL CRACK, ON THE HINGE SIDE. IF BUILDER SAYS THEN ORDER FIX IT	LL CRACK, ON THE H	INGE SIDE. IF BUILI	DER SAYS THEN ORD	DER A SLAB AND BUILDER WILL	JILDER WILL
PARTS REQUIRED					
LN Item Description 81 2' 10" CLAD DOOR SYS	Location ENT	Specification SLABS (ALL)	Size Options 35.75 X 81.75 RIGHT SQUAF	Options RIGHT STEEL 2PNL SQUARE TOP TYPE1 DW	OW of
82 623_STYLE DOORLITE	ENT	9 :	***************************************		į
Problem Description:	ilder to	respunt	Front Don	75/2	2
Warranty Material S		☐ CHARC	CHARGEABLES aterial \$	50	
Labour \$	/	Labour \$			
	90	P.O.#:			
Cause:	,		Š		
Solution:			no Rack end	755	
					,
Date Completed:	18/21	Approved:	wed: X Ward	Mo Signack	Squatore
Time:		Service Signature:	iture:	\$TEVE	