



Work Order

Tue Feb. 23
9am-11am

Address: 1534 Angus St.

Innisfil, Ontario

Innisfil, Ontario

Today's Date: 18Dec20

Email: chrissoares836@gmail.com

Dina
contact
dinaschemb@gmail.com

New Image Kitchens

Telephone: (416) 739-0007

(416) 739-7031

Please Complete the following items:

1 DOOR	1 DOOR
F0501TE 2	2 400000 1 DOOR
1 DOOR	2 BASE
	2 400000 1 DOOR
	2 400000 1 DOOR

Feb 23, 2021

Liara Chen

Feb 23/2021

Trade &/or Service Tech.

Signature: A. S. [Signature]

Print Name: Arjun

Outstanding Deficiencies
Belle Aire Shores - Phase: 1 - Lot: 9 - Model: RIDGE (50-04) ELEV A

Date Reported	Type	Number	Deficiency Description	Trade Assigned	Add	Appointment Date
14Dec20	PDI	1	Master Ensuite- General- OVERCUT TILE AT SHOWER DRAIN	AV Classic 141472	Add	NoAppointment
14Dec20	PDI	2	Master Ensuite- General- BLEMISH ON 15TH TILE FROM BOTTOM (SHOWER WALL) ACROSS FROM WATER CONTROLS	AV Classic 141473	Add	NoAppointment
14Dec20	PDI	3	Master Ensuite- General- CHIP ON LEFT SIDE OF COUNTER (REPAIR UNACCEPTABLE)	New Image Kitchens 141474	Add	NoAppointment
14Dec20	PDI	4	Master Bedroom- General- REQUIRE LIGHT (EXTRA) IN CLOSET	Dart Electric 141475	Add	NoAppointment
14Dec20	PDI	5	Bedroom 3- General- MOVE LIGHT SWITCH IN CLOSET	Dart Electric 141476	Add	NoAppointment
14Dec20	PDI	6	Upper Hall- General- ADJUST TOP AND BOTTOM BRACKET AT LINEN (SHELVING BOWED)	WYECROFT TRIM 141477	Add	NoAppointment
14Dec20	PDI	7	Master Ensuite- General- SHOWER GLASS-INSPECT TOP SECTION, LOOKS OUT OF SQUARE (INSTALLED DEC 10)	Central Glass 141478	Add	NoAppointment
14Dec20	PDI	8	Family Room- General- 2 CREASES VISIBLE ON FIREPLACE SCREEN AND TOUCH UP PAINT AT TOP LEFT CORNER	National Fireplaces and Facings INC. 141479	Add	NoAppointment
14Dec20	PDI	9	Kitchen- General- SCRATCHES ON BOTTOM OF SINK	Icon Plumbing & Heating 141480	Add	NoAppointment
14Dec20	PDI	10	Kitchen- General- H/O QUEARY--APRON SINK SHOULD BE PUSHED BACK, REVEAL INCORRECT.	Redstone Marble 141481	Add	NoAppointment
14Dec20	PDI	11	Kitchen- General- CHIP ON ISLAND, FACIN SINK	New Image Kitchens 141482	Add	NoAppointment
14Dec20	PDI	12	Kitchen- General- PAINT PITTD ON UPPER DOOR, 3RD LEFT OF STOVE (REPAIR UNACCEPTABLE)	New Image Kitchens 141483	Add	NoAppointment
14Dec20	PDI	13	Exterior- General- H/O QUEARY--BRICK COLOUR INCONSISTENT	Unit-ri 141484	Add	NoAppointment