Purchaser Name: Alexey Kaspin **Enrollment:**

Phone Bus:

Closing Date: Inspector: Antonella Lucchesi February 07, 2019

ZANCOR

Project: Zancor Homes (Innisfil) Ltd

Lot / Phase: 83N / 2

Address: Plan:

Municiaplity: Inspection Date: January 29, 2019

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS), Please initial all changes and deletions. As a minimum, check the following:

Page 1 of 2

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens Bathtub sinks and toilets

- Bathroom accessories if provided Mirrors, counter tops and cabinetry Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Hot water heater, if provided (not rental) Exterior finished, driveways, walkways, d

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
 Faucets: Kitchen, bathroom, laundry room
 Exhaust fans (kitchen, bathrooms) if provided
 Electrical outlets and fixtures
 Gas fireplaces, incl.circulation fans, if provided

- Heat Recovery Ventilation system, if provided Heating system Hot water heater, if provided (not rental) Air conditioning system, if provided and if cond

MASTER ENSUITE BATH		×.
	TILE IN WATER CLOSET NEEDS TO BE CUT TO FIT HEAT REGISTER GOUGE ON WALL ABOVE HEAT REGISTER	
MASTER BEDROOM		
	REMOVE STIPPLE OFF FLAT CEILING INSIDE WALK-IN CLOSET BY ATTIC HATCH CLEAN WINDOWS AT EXTERIOR THROUGHOUT THE HOUSE NAILS STICKING OUT ON WINDOW CASING	***
UPPER HALL		*
FOVER/HALL	ADJUST LINEN CLOSET DOORS	V AL
	FILL GAP ON THE OUTSIDE STRINGER AT STAIRS TO 2ND FLOOR GAPS ON HARDWOOD FLOOR AT ENTRANCE BY TILES AND MAIN HALLWAY	××
EXTERIOR		
	PAINTING NOT COMPLETE	×
POWDER ROOM		
	SCRATCH ON ONE TILE AT THE LEFT SIDE OF TOILET	A

Homeowner digesture: The Homeowicer acknowledges and accepts that all initialed work has been completed in a workman like manner to their satisfaction

TANEX DIO PERBIGUELLA GLASS FROM SILL