

PRINTED ON: 09/29/21 09:27AM

PRINTED BY: dtrinh

JELD-WEN
Field Service Work Order

DISPATCHED BY:
Sally Shmoon

REFERENCE: 11H21B32:8
ORDER: NZ 527483
DATE: 09/15/21
ID: sshmoon
ORIG ORDER: UW 919172
PURCH DATE: 06/11/18

VAUGHAN, ON L4H 3G9
PHONE: 844-355-5760
FAX: 9057385748

SOLD TO: 063948
ZANCOR HOMES (COOKSTOWN) LTD
PROJ: COOKSTOWN 221 NORTH RIVERMED
CONCORD, ON L4K 3N7
PHONE:
FAX:

PROVIDER: 02561
JW-UW (Dawd)
90 Stone Ridge Rd
Vaughan, ON L4H3G9
Voice: 905/265-5700
Fax: 905/265-5704

JOB SITE ADDRESS:
Krishnaveni Sathiyabama
19 mumberson st
cookstown, ON l0l
Subdiv/Proj: cookstown
Phase: 1
Primary Phone: 416 316 7900
Alternate Phone: 416 277 0315

SHIP TO: 063948
JW TECH / DAWD
90 Stone Ridge Road
Vaughan, ON L4H 3G9

Lot: 20

BUSINESS: ZANCOR HOMES (COOKSTOWN) LTD
Gidella Fiore
Primary Phone: 905 738 7010
Fax:
EMail:

CUSTOMER NO: 063948

BUILDER:
Primary Phone:
EMail:

Done

GENERAL INFORMATION: Dai# 145135

kitchen - general - item:
 #1 back porch door has leak coming through
 balcony door at teh top bottom

per tech note: Inspection: The breakfast area
 garden door has been inspected. The door Toplite
 and both
 sidelite glasses had poor clear silicone and
 separate from glass not sealed properly. Also the
 8'
 inserts were not installed properly. Has to be
 reinstalled. The door installation screws capping
 are missing. As per homeowner when he spray water
 on the door.It's leaking.
 Please rebook appointment with 2- man crew to
 remove all the poor and damaged silicone -frame
 the glass and re-silicone the sidelite and
 toplite. Also Secure the 8 feet inserts and
 replace the garden door weather stripping. Also
 installed the door frame installation screws
 capping.Pictures are attached.

Done

Done

Done

CUSTOMER SIGNATURE: _____

DATE: **Sept.30.2021**

* signature confirms the work listed above has been completed to my satisfaction

MANUFACTURING ORDER:
 UW : 1096964

PARTS SHIP	CUSTOMER PO	SHIP VIA	WARRANTY DETERMINATION	TASK DUE DATE
10/01/21	NZ527483	Company Trk	Labor only	10/01/2021

*****Additional Comments*****

Lot:
 PO:

LINE	ITEM DESCRIPTION	QTY	ORD	HOURS	EXT HOURS
1	*Serv101 Setup-Cleanup-Cust Interaction NOTE: JOB/TAG NAME: lot 20 - 11h21b32 Quebec QST #1022276197 TQ0001 MB PST #872627195 MT0004 SK PST #1474196 BC PST #1014-0681	2		0.25	0.50
2	*Serv37 Labor adjustment-increase NOTE: JOB/TAG NAME: lot 20 - 11h21b32 Quebec QST #1022276197 TQ0001 MB PST #872627195 MT0004 SK PST #1474196 BC PST #1014-0681	16		0.25	4.00
3	P55889 Mfg: uw	1		0.00	0.00

V Vinyl Install Plugs 8'-Dbl36" Black)** Dept: UWS
NOTE: JOB/TAG NAME: lot 20 - 11h21b32
Quebec QST #1022276197 TQ0001
MB PST #872627195 MT0004
SK PST #1474196
BC PST #1014-0681

*****Additional Comments*****
JOB/TAG NAME: lot 20 - 11h21b32