

Brody Guenther

Service Work Order

Number: 36003
Entered: 10/15/2021

TRUDEL & SONS ROOFING LTD.

5 Paisley Lane
Stouffville, ONT L4A7X4

Duplicate

Service

Location:

Zancor Homes- BELLE AIRE SHORES
LOT 38N
1777 EMBERTON WAY
INNISFIL ONT

Contacts:

Phone:
Mobile:

Bill To:

Zancor Homes
221 North Rivermede Rd.
Concord, ONT L4K 3N7

PO Number:

Payment Method: Bill Out
Customer Code: ZANC

Call Type:

Repair

Est. Hours/Priority:

1.00

Problem:

Builder Work Order See Attached

Permission Code:

Homeowner

Scheduled:

10/15/2021

Scheduled Time:

8:00 am

Technician:

Brody Guenther

Job Priority:

High

Fax Back No:

Service Dept Comments:

LOOSE FLASHING AND ROOF TOP ROOF VENT DEFORMED.

Parts:

(To Be Filled In By Technician)

Labour:

(To Be Filled In By Technician)

Comments & Notes: (Technician)

To Do Items:

Work Order Notes:

THE VENT CLIPS WHERE LOOSE, FIXED THIS. FIXED FLASHING THAT HAD LIFTED DUE TO SIDERS INSTALLATION OF MATERIAL. FIXED THIS AREA ALSO.

COMPLETED OCT. 14/21
LOT 38N - BELLE AIR SHORES