## Outstanding Deficiencies For Toronto Concrete & Drain Company-Wide

Print Session: 634 - Printed: 190ct21

WO Date	Cot	Phase	Site	Type	Deficiency Description	DAI	Appt. Date	Days	Initial
								O <sub>L</sub>	
16Jul21	16Jul21 Block 135	200	The Village of Trillium   1 Year	1 Year	Exterior- General- Item #2- cement	145118	145118 NoAppoint.	95	
	Unit 1	U	Forest		chipped by asphalt from pavers		·		
12Aug21	12Aug21 Block 140	2	The Village of Trillium 30-Day		ps left	145414	145414 23Sep21	68	
	Unit 3	9	Forest		of front door at front porch				
070ct21	on O	-3	Cookstown	Interval	Exterior- General- Garage floor by pillar   145948   NoAppoint.	145948	$\rightarrow$	12	
					at garage cracked				
07Oct21 26	26	_	Cookstown	1 Year	Exterior- General- Item #23- stairs-	145974	290ct21	12	
					poured concrete stairs have incomplete				
					concrete work- Drip marks on steps				