

## NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6 TEL (905) 672-1233 FAX (905) 672-1076 WO # W145557

Service Date: Nov 01, 2021

	di:	1150	0		
Priority: Normal		Status:	SCHEDULED		
BUILDER					
Customer: 611383 Name: ZANCOR WASAGA TOWN Service Fax: Site Fax:	S	City: Service Phone(s): Site Phone: Lot#:	WASAGA BEACH	Received: Time: Order: Phase:	Oct 12, 2021 1ST CALL D369310-1
RESIDENT INFORMATION		LOW.	BLK 141 - 3	Filase.	
Home Owner Name: PRECILLA DE BAI	PPOS IDMAO	Address	31 BIANC	A CRES	
Home Phone(s): 647-898-7584 Cell Phone(s):	WOO II WIAO	Work Ph Email(s)	9 ss. #		
LINKED ORDER INFORMATION				orother@gmail.com	Ser.
Customer: 611383 ZANCOR WASAGA Model: TH-5/ OPT. 4B / SW	TOWNS		Lot #: BLK Phase:	141 - 3	,
SERVICE INSTRUCTIONS				1 10-	
BEDROOM 3: GENERAL ITEM#2 - SCRE	EN DOES NO	T FIT IN WINDOW	WRONG SIZE.	Brus let	2
PARTS REQUIRED	f.		THE HIER		
LN Item Description 152 NEWMAR VINYL CASEMENT	Location B3	Specification SCREENS-REP CEMENT-WIND WS		Options	Qty 1
Problem Description:					
Warranty		1113	RGEABLES		7.7
Material \$	Å.	Material	1//		
Labour \$		Labour	\$		
Cause:		P.O.#;	1 000	1	Man.
					- 96
Solution:			H/0 S	igualiore.	à: d
Date Completed:	ir as	App	proved: ** Rus	wille J.	maio
Time: 157cm		Service Sig	nature:	The state of the s	V I
				STEVE	



## NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

WO # W143249

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6 TEL (805) 672-1233 FAX (905) 672-1076 Service Date: Sep 21, 2021

Priority:	Normal			Status:	COMPLETE	D	*
BUILDER Customer:	611383			Cit	1414 CA CA DI	EACH Received	d. Com 42 2024
Name:		R WASAGA TOWNS		City:	WASAGA BE	EACH Received	d: Sep 13, 2021 AM
Service Fax:	ZANCO	N WASAGA TOWNS	•	Service Phone( Site Phone:	8).	Order:	D369310-1
Site Fax:				Lot#:	BLK 141 - 3	Phase:	D2082 10-1
RESIDENT	INFORM	ATION		LOUP.	BLK 141 - 3	rilase.	
Home Owner		PRECILLA DE BAR	ROS IRMAO	Addre	ss: 31 B	IANCA CRES	- g 1
Home Phone(s): 647-898-7584		Work Phone(s):					
Cell Phone(s):			Email(s): prescilla.brother@gmail.com				
		ORMATION					
Customer:	611383 Z	ANCOR WASAGA 1	OWNS		Lot #:	BLK 141 - 3	
Model:				Phase:			
SERVICE IN	STRUC	TIONS					
BEDROOM 2	- GENER	AL ITEM #2- SCREE	N DOES NO	T FIT IN WINDO	WWRONG SIZE	T (1)	Onci
PARTS REC						1000	15110
LN Item Desc	ription		Location	Specification	Size	( John CO	~ racontion
162 NEWMA	AR VINYL	CASEMENT	B2		PLA 25.0625 X	0	2 11001
				CEMENT-WIN	IDO 47.125	+KOO,	Diduce
				WS		Should	1- ROG
Problem Desc	crintion:					01000	- 3
T TODICITI DOSC	Shption,					Red	roon
Warranty				ПСН	ARGEABLES		
Material \$				Mater	ial \$		v Q
Labour \$				Labou	ır \$	- rongs	Tun.
				P.O.#	:	0/60	16 D
Cause:						A	<u>yer</u>
Solution:					370	7	
Ooldtion.				11174			
Date Completed:			A	pproved:			
Ī	Time;			Service S	ignature:	STEVE	
						SIEVE	