

Brody Guenther

Service Work Order

Number: 35735
Entered: 8/27/2021

TRUDEL & SONS ROOFING LTD.

5 Paisley Lane
Stouffville, ONT L4A7X4

Duplicate

Service

Location:

Zancor Homes - BELLE AIRE SHORES - INNISFIL
LOT 40N
INNISFIL,ONT
INNISFIL ONT

Contacts:

Phone:
Mobile:

Bill To:

Zancor Homes
221 North Rivermede Rd.
Concord, ONT L4K 3N7

PO Number:

Payment Method: Bill Out
Customer Code: ZANC

Call Type:

Repair

Est. Hours/Priority:

1.00

Problem:

Builder Work Order See Attached

Permission Code:

Homeowner

Scheduled:

8/27/2021

Scheduled Time:

8:00 am

Technician:

Brody Guenther

Job Priority:

High

Fax Back No:

Service Dept Comments:

INSPECT ROOF AS PER INSPECTION FOR LIFTING SHINGLES.

Parts:

(To Be Filled In By Technician)

Labour:

(To Be Filled In By Technician)

Comments & Notes: (Technician)

To Do Items:

Work Order Notes:

INSPECTED ROOF AREA AND HAMMERED DOWN SOME NAIL HEADS.

COMPLETED NOV. 2/21
LOT 40N - BELLE AIR SHORES