

Monday Dec 20 @ 8am



Zancor Homes (Innisfil) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date: 11 Aug 20

Address: 1767 Emberton Way

Innisfil, Ontario

Location: Belle Aire Shores - Phase: 2 - Lot: 36N

Today's Date: 17 Dec 21

Contact(s):

Nuno, Filipe Lima - Home: (416) 993-3307 - (84.lima.nuno@gmail.com)

Caroline, J Lima - Home: (416) 856-2276 - (caroline.jv.lima@gmail.com)

Email: 84.lima.nuno@gmail.com

Company: Zancor - Innisfil Warranty Service

Attention:

Telephone:

Fax:

Please Complete the following items:

DAI	Type	Issue	Appt. Date/Time	Notes
146573	Interval	Living Room- General- inspect hardwood in living area. homeowner advised are is squeaking again	20 Dec 21 /am	Arrival at 8am.

Date Completed:

Homeowner Signature:

The Homeowner acknowledges and accepts all work
has been completed in a workman like manner

Date Completed:

Trade &/or Service Tech.

Signature:

Print Name:

Please schedule your Service Department to complete work on the above Lot. Should no
appointment time or date appear (below) on this form, it is your responsibility to arrange and
adhere to the appointment you have scheduled. Your service representative must have this form
signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and
it's group of companies) the right to carry out any and all repairs. All costs incurred will be
applied to the Company listed above.

Re Book - Zancor + Kingsview 3/4 of the Day

146495	1 Year	squeaking still not fixed from the 30 day from near kitchen	Other- General- Item #14- trim hallway opening on top not painted properly and is visible with light	03Dec21 /am	
146498	1 Year	Main Bathroom- General- Item #17- there's a lot of door frame trims tracks that need to be caulked		03Dec21 /am	
146501	1 Year	Stairs- General- Item #20- caulking missing around the stair trim		03Dec21 /am	
146502	1 Year	Stairs- General- Item #21- garage concrete wall spray paint still left from the construction in big letters		03Dec21 /am	
146503	1 Year	Exterior- General- Item #22- the bottom of the garage door seal doesn't completely seal from one side from the outside		03Dec21 /am	
146575	Interval	Stairs- General- SVC TO MEASURE THRESHOLD AT STAIRS AND HUMIDITY..		20Dec21 /am	ARRIVAL 10AM 15MM FROM THE LAMINATE SIDE 7MM FROM THE NOSSING SIDE HUMIDITY - AVERAGE - 40%

Date Completed: _____

Homeowner Signature: _____

The Homeowner acknowledges and accepts all work has been completed in a workman like manner

Date Completed: Dec 20/21

Trade &/or Service Tech. _____

Signature: _____

Print Name: BOUMEN

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and