


Outstanding Deficiencies

Now Towns In Brooklyn - Phase: 1 - Lot: Unit 14 (Block 2)

<u>Date Reported</u>	<u>Type</u>	<u>Number</u>	<u>Deficiency Description</u>	<u>Trade Assigned</u>	<u>Add Trade</u>	<u>Appointment Date</u>	<u>Item Completed</u>	<u>Initial</u>
<u>25Feb22</u>	PDI	1	Kitchen- General- Chip on upper left cabinet left of stove	<u>New Image Kitchens</u> 146807	<u>Add</u>	<u>NoAppointment.</u>	✓	<u>AM.</u>
<u>25Feb22</u>	PDI	2	Kitchen- General- Chip on lower right garbage door left of sink	<u>New Image Kitchens</u> 146808	<u>Add</u>	<u>NoAppointment.</u>	✓	<u>AM.</u>
<u>25Feb22</u>	PDI	3	Kitchen- General- Chip on right island gable right of sink (Bottom)	<u>New Image Kitchens</u> 146809	<u>Add</u>	<u>NoAppointment.</u>	✓	<u>AM.</u>
<u>25Feb22</u>	PDI	4	Kitchen- General- 2 Chip on left gable at electrical outlet and base	<u>New Image Kitchens</u> 146810	<u>Add</u>	<u>NoAppointment.</u>	✓	<u>AM.</u>
<u>25Feb22</u>	PDI	5	Kitchen- General- Chip on lower left cabinet at sink	<u>New Image Kitchens</u> 146811	<u>Add</u>	<u>NoAppointment.</u>	✓	<u>AM.</u>
<u>25Feb22</u>	PDI	12	Basement- General- Inspect ceiling in cold room. Light coming through	<u>Toronto Concrete & Drain</u> 146818	<u>Add</u>	<u>NoAppointment.</u>		
<u>25Feb22</u>	PDI	13	Exterior- General- Painting not complete at exterior	<u>Perfect Touch Painting</u> 146819	<u>Add</u>	<u>NoAppointment.</u>		

Homeowner Signature: 

The Homeowner acknowledges and accepts that all installed work has been completed in a workman like manner to their satisfaction.

Date: _____

Zancor Service Technician: _____