






Outstanding Deficiencies **Now Towns In Brooklyn - Phase: 1 - Lot: Unit 12 (Block 2)**

<u>Date Reported</u>	<u>Type</u>	<u>Number</u>	<u>Deficiency Description</u>	<u>Trade Assigned</u>	<u>Add Trade</u>	<u>Appointment Date</u>	<u>Item Completed</u>	<u>Initial</u>
<u>10Feb22</u>	PDI	3	Stairs- General- CHIP @ FIRST TREAD AT STAIRS TO 2ND FLOOR AND CHIP TREAD AT 1ST, 2ND , 3RD TREAD AT STAIRS TO 3RD LEVEL	<u>Stairfab</u> 146732	<u>Add</u>	<u>NoAppoint.</u>	✓	
<u>10Feb22</u>	PDI	5	Stairs- General- Cracked stringer at 8th step at stairs to 3rd floor	<u>Stairfab</u> 146734	<u>Add</u>	<u>NoAppoint.</u>	✓	
<u>10Feb22</u>	PDI	8	Exterior- General- exterior painting not complete	<u>Perfect Touch Painting</u> 146737	<u>Add</u>	<u>NoAppoint.</u>		
<u>01Apr22</u>	Interval	1	Stairs- General- STAIN REQUIRED AT STAIRS DUE TO STAIRFAB REPAIR	<u>Perfect Touch Painting</u> 147181	<u>Add</u>	<u>NoAppoint.</u>	✓	

these@pr12@yahoo.co

<p>Homeowner Signature: </p> <p>The Homeowner acknowledges and accepts that all installed work has been completed in a workman like manner to their satisfaction.</p> <p>Date: <u>4/6/22</u></p> <p>Zancor Service Technician: </p>
--