Fax: (905) 738-5948

Work Order

Glosing Date: Address:

Location: Today's Date: 27Nov20 Blanca Crescent Wasaga Beach The Village of Trillium Forest - Phase: 3 - Lot: Block 134 Unit 4

08Apr22

Contact(s): Shawna Leigh Thomson - Home: (705) 241-8113 - (just\_shawna@yahoo.ca) Alf, B Pistolkors just\_shawna@yahoo.ca

Email:

Wasaga Zancor Warranty Service

Company:
Attention:

Telephone:

(705) 428-6483 (705) 428-6484

DAI	Type	Issue		Appt. Date/Time	Notes
146522	1 Year	Foyer- General- Crack between drywall and ceiling at front entrance	-	11Apr22 /am	
146525	1 Year	Living Room- General- Squeak at front entrance as per H.o SVC to inspect		11Apr22 /am	
146526	1 Year	Basement- General- SVC inspect behind insulation below window for crack( Mud visable)		11Apr22 /am	

Date Completed: 📈

Homeowner Signature: The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Signature:

Trade &/or Service Tech

Date Completed:

Print Name:

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

## Outstanding Deficiencies The Village of Trillium Forest - Phase: 3 - Lot: Block 134 Unit 4

13Dec21	<u>08Dec21</u>	08Dec21	08Dec21	08Dec21	08Dec21	<u>Date</u> Reported
l Year	l Year	l Year	l Year	l Year	l Year	Туре
6	<b>י</b> א	4	ယ	2	<b>J—1</b>	Number
Kitchen- General- Kitchen facuet drips	Basement- General- SVC inspect behind insulation below window for crack (Mud visable)	Living Room- General- Squeak at front entrance as per H.o SVC to inspect	Living Room- General- Film between two panes to be inspect in warmer weather middle window below transom	Master Ensuite- General- Cracked grout in ensuite shower	Foyer- General- Crack between drywall and ceiling at front entrance	Deficiency Description
Plumbing & Heating 146534	Wasaga Zancor Warranty Service 146526	Wasaga Zancor Warranty Service 146525	<u>Newmar</u> 146524	AV Classic 146523	Wasaga Zancor Warranty Service 146522	Trade Assigned
Add	Add	Add	Add	Add	Add	Add Trade
11.Apr22	11Apr22	11Apr22	20Apr22	11Apr22	11Apr22	Add Appointment
						Item Completed
	8	P		The state of the s	R	Initial

Homeowner Signature

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Zancor Service Technician: