Enrollment:

Purchaser Name: Paolo, Ruiz Espinoza

Christopher, Bri Alano

Phone Res:

Phone Bus: (289) 200-0268 Closing Date: April 18, 2022 Inspector: Gisella Fiore

HOMES

Vendor / Builder:

Project: Zancor Homes (Parkview) Ltd.

Lot / Phase: Unit 28 (Block 5) / 1

Plan: Address: Municiaplity:

Inspection Date: March 28, 2022

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

-			
MASTER ENSUITE BATH			
MIRROR	MIRROR NOT INSTALLED THROUGHOUT	_	
VANITY CABINETS	SMALL CHIP ON RIGHT VANITY GABLE	 _	
COUNTERTOPS	RIGHT VANITY LAMINATE COUNTERTOP PEELING	 _	
WALLS	CHIP ON SHOWER GLASS AT MARBLE LEDGE	 _	
MASTER BEDROOM			
FLOORING	WRONG HEAT REGISTER INSTALLED LEFT OF BALCONY DOOR	 	
	FLOOR SQUEAK IN HARDWOOD 4TH PLANK FROM HEAT REGISTER	 _	
BEDROOM 2 ENSUITE			
FAUCETS/PLUMBING	SINK NOT HOLDING WATER . FAUCET STUCK	 	
UPPER HALL			
RAILING	CHIP ON 1ST RISER BELOW 1ST NOSING AT 1ST LANDING TO SECOND FLOOR / NOSING RIGHT	 	
	OF NEWEL POST CHIPPED		
FLOORING	FILLER NOT INSTALLED AT NEWEL POST AT MAIN FLOOR AND 2ND FLOOR	 _	
KITCHEN			
CABINETS	REMOVE FILM RESIDUE OFF UPPER CABINETS IN KITCHEN	 =	
FOYER/HALL			
FLOORING	SCRATCH ON 2ND HARDWOOD PLANK IN FRONT OF NEWEL POST AT MAIN FLOOR STAIRS	 	
FRONT DOORS	BUBBLE ON BOTTOM OF DOOR LEFT SIDE	 _	
	DOOR BELL NOT WORKING	 _	
EXTERIOR			
PORCH	ALUMINUM SIDING AND SOFFIT NOT INSTALLED AT FRONT PORCH	 _	
DECK	NOT INSTALLED AT REAR OF HOME AT 2ND FLOOR	 _	
PAINT	PAINTING NOT COMPLETE AT EXTERIOR	 _	

Enrollment:

Purchaser Name: Paolo, Ruiz Espinoza

Christopher, Bri Alano

Phone Res:

Phone Bus: (289) 200-0268
Closing Date: April 18, 2022
Inspector: Gisella Fiore



Vendor / Builder:

Project: Zancor Homes (Parkview) Ltd.

Lot / Phase: Unit 28 (Block 5) / 1

Plan: Address: Municiaplity:

Inspection Date: March 28, 2022

Page 2 of 2

A REFERENCE FOR FUTURE WARRAN	TY REQUESTS. esignate someone to conduct the PDI in the	HOME'S CONDITION BEFORE THE PURCHASE eir place should ensure they provide written autho					
I have inspected my new home and I agree that the description of the items listed on this form are accurate.							
Paolo, Ruiz Espinoza	GA -	Christopher, Bri Alano					
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature				
		Gisella Fiore	STOR				
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature				
Date (YYYY/MM/DD)	2022/03/28	March 28, 2022					