Enrollment:

Purchaser Name: Neha Sharma

Shailendra Kumar Sharma

Phone Res:

Phone Bus: (289) 838-4870 Closing Date: April 21, 2022 Inspector: Gisella Fiore

HOMES

Vendor / Builder:

Project: Zancor Homes (Parkview) Ltd.

Lot / Phase: Unit 64 (Block 10) / 1

Plan: Address: Municiaplity:

Inspection Date: April 14, 2022

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

FOYER/HALL		
STAIRS	X2 PICKETS NOT INSTALLED AT STAIRS FROM MAIN FLOOR TO 2ND FLOOR BY 2ND TREAD RIGHT SIDE	
	CRACK ON 1ST TREAD AT STAIRS FROM MAIN FLOOR TO 2ND FLOOR BY PICKET/ CRACK ON	
	8TH TREAD AT STAIRS FROM 2ND FLOOR TO 3RD FLOOR / CRACK ON INSIDE STRINGER AT 9TH	
	TREAD AT STAIRS FROM 2ND FLOOR TO 3RD FLOOR	
FLOORING	SCRATCH ON X3 PLANK INFRONT OF ENTRANCE TO POWDER ROOM	
KITCHEN		
COUNTERTOPS	NOT INSTALLED THROUGHOUT HOUSE	
SINK/FAUCET/PLUMBING	PLUMBING NOT COMPLETE DUE COUNTERTOPS NOT BEING STALLED IN KITCHEN/ MASTER ENSUITE / 2ND ENSUITE	
CABINETS	SMALL CHIP ON UPPER RIGHT CABINET RIGHT OF STOVE	
EXTERIOR		
PAINT	PAINTING NOT COMPLETE AT EXTERIOR	
	GARAGE	
GARAGE DOORS	GARAGE DOORS NOT INSTALLED	 <u> </u>
DECK	EXTERIOR RAILINGS AT 2ND FLOOR PATIO NOT INSTALLED	 <u> </u>
	AC NOT INSTALLED	
MASTER BEDROOM		
WINDOWS	RIGHT MULLIN BUBBLED	
POWDER ROOM		
TRIM	ADJUST POWDER ROOM DOOR AT MAIN FLOOR CANNOT CLOSE SECURE HINGE	
BASEMENT		
-	REPAIR FIRST TREAD AT STAIRS IN BASEMENT BROKEN AS COURTESY	

Enrollment:

Purchaser Name: Neha Sharma

Shailendra Kumar Sharma

Phone Res:

Designate's Name (print)

Date (YYYY/MM/DD)

Phone Bus: (289) 838-4870
Closing Date: April 21, 2022
Inspector: Gisella Fiore



Page 2 of 2

Vendor / Builder:

Project: Zancor Homes (Parkview) Ltd.

Inspector's Signature

Lot / Phase: Unit 64 (Block 10) / 1

Plan: Address: Municiaplity:

Inspection Date: April 14, 2022

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS. * Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.					
I have inspected my new home and I agree that the description of the items listed on this form are accurate.					
Neha Sharma	Shall	Shailendra Kumar Sharma			
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature		
		Gisella Fiore	H/6)		

Inspector's Name (print)

April 14, 2022

Designate's Signature

2022/04/14