

Pre-Delivery Inspection (PDI) Form

SITE: Barton
LOT #: 13
ENROLMENT # H 3505105

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any "substitutions" of items referred to in, or to be selected under, the Agreement of Purchase and Sale (APS).

PAGE #: 1 OF

Item #	Room/Location	Description
PS ✓	DOOR	GLASS INSERTS @ FRONT DOOR TO BE FROSTED.
PS ✓	STAIRS	Inspect Post @ stairs to 2nd floor (shaking).
PS ✓	SHARED BATH	Vent above toilet cracked
4	living hall	chip on 7th plank left of entrance @ another
5	Master Bath	Scratch on left fixed glass below hinge
PS ✓	"	Marble seat in shower scratched
PS ✓	STAIRS	chip on 6th tread @ stairs to 2nd floor
PS ✓	Kitchen	Bulbhead above left cabinet of hood fan cracked.
PS ✓	Living Room	Scratches on fireplace
PS ✓	exterior	1. Extend siding not complete
PS ✓		2. Soffit fascia throughout not complete
		3. Exterior Painting not complete

Purchaser's signature _____

Date (YYYY/MM/DD) 2022, 02, 14