

The items listed below were released to the homeowner(s) of

Lot # 8	Site/Phase: Brampton The Reggive of
/ House and Garage Door Keys	Complete 1 sources
< Homeowner Manual	
_N/A_ Recycling and Green Bins	
N/A Other freplace remote	
The above items were received on this losh day of June.	byth room accessivies as per extra sheet #7 (14941 bar 182424 (1)x To hake 182408.  ems were received on this loth day of June. 2022
Swhing & d.	

The

Purchaser

Purchaser

Purchaser Name: **Enrollment:** Sukhraj Dhillon

Closing Date: Phone Bus: Phone Res: (905) 230-5658 June 06, 2022 (647) 984-7525

HOMES

ANCOR

Vendor / Builder:

Project: 8/1 Zancor Homes (Brampton) Ltd.

Lot / Phase: Plan:

Address:

Municiaplity: Inspection Date: June 02, 2022

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

Page 1 of 2

## DAMAGED, INCOMPLETE OR MISSING

- lights and other glazing. Window and door screens
- Bathrub sinks and toilets
  Bathroom accessories if provided

- Mirrors, counter tops and cabinetry Flooring (hardwood, vinyl, ceramic tiles, carpeting) Interior finished and tim carpentry

- Hol water heater, if provided (not rental)

  Exterior finished, driveways, walkways, decks and landscaping

## **OPERATING CONDITION**

- Windows, interior and exterior doors. Door locks Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided Electrical outlets and fixtures

- Gas fireplaces, incl.circulation fans, if provided Heat Recovery Ventilation system, if provided
- Heating system

  Hot water heater, if provided (not rental)

  Air conditioning system, if provided and if conditions permit
- MASTER ENSUITE BATH SCRATCH ON RIGHT MARBLE SIDE SPLASH
  SMALL CHIP ON LOWER RIGHT CABINET BELOW RIGHT AND SINK AND BELOW LOWER RIGHT
  SINK LEFT DOOR
- BEDROOM 2 ENSUITE VANITY CABINETS LAUNDRY ROOM CRACK ON COUNTERTOP LEFT OF SINK SIDE SPLASH RIGHT OF SINK LIFTING ADJUST CARPET SHIM AT ENTRANCE TO SHARED BATH
- UPPER HALL BEDROOM #3 COUNTERTOPS STAIN ON CARPET IN FRONT OF RIGHT WINDOW
- BASEMENT CABINETS KITCHEN ADJUST UPPER CABINET ABOVE HOOD FAN RIGHT AND AND UPPER RIGHT DOOR RIGHT OF HOOD FAN AND AT ISLAND
  SCRATCH ON LOWER LEFT CABINET RIGHT OF GARBAGE BIN VARNISH REQUIRED AT UPPER FLOOR RAILING 2) VARNISH REQUIRED SCRATCH AT NEWEL POST AT 2ND LANDING AT STAIRS TO 2ND FLOOR
- NOTE PAINT EXTERIOR NOT COMPLETE
  EAVES NOT INSTALLED AT FRONT OF HOUSE DENT ON SEPARATE ENTRANCE DOOR BY BASEMENT

RAILING

\* - O A/C unit installed were 6th/22

Enrollment:

Purchaser Name: Sukhraj Dhillon

Phone Res: (647) 984-7525
Phone Bus: (905) 230-5658
Closing Date: June 06, 2022
Inspector: Gisella Fiore

ANCOR

HOMES

Page 2 of 2

Vendor / Builder:

Project: Zanco Lot / Phase: 8 / 1 Plan: Zancor Homes (Brampton) Ltd.

Address:

Municiaplity: Inspection Date: June 02, 2022

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

\*Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendorbuilder authorizing the designate to sign this form on their behalf:

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

Moundy

Sukhraj Dhillon

Purchaser's Name (print)

Purchaser's Signature

Purchaser's Name (print)

Gisella Fiore

Inspector's Name (print)

June 02, 2022

Date (YYYY/MM/DD) Designate's Name (print)

2022/06/02

Designate's Signature

Purchaser's Signature

Inspector's Signature