Zancor Homes (Brampton) Ltd. Warranty Services

Fax: (905) 738-5948 Phone: (905) 738-7010

Work Order

Closing Date: 06Jun22

Address:

Location: Reserve Of Country Trails - Phase: 1 - Lot: 8 09Jun22

Today's Date: Contact(s): Sukhraj Dhillon - Home: (905) 230-5658 Cell: (647) 984-7525 -

(hkdhillon76@gmail.com) hkdhillon76@gmail.com

Email:

Company:
Attention: Zancor - Brampton Warranty Service

Telephone:

Fax:

Please Complete the following items:

DAI	Туре	ssue		Appt. Date/Time	Notes
148025	Interval	Foyer- General- touch up chips on astracal at front door above hinge		22Jun22 /am	
148026	Interval	Foyer- General- Dent on front door right side noted on walkthrough at key pick up		22Jun22 /am	
148027	Interval	Main Hall- General- Small dent on drywall mud room left of door		22Jun22 /am	
148078	Interval	Bedroom 2 Ensuite- General- Touch up cracked trim		22Jun22 /am	
148079	Interval	Powder Room- General- Small area in powder room missing grout		22Jun22 /am	
148080	Interval	Foyer- General- Front door required to be adjusted	(\$	22Jun22 /am	
148081	Interval	Bedroom 2 Ensuite- General- Caulk around	12	22Jun22 /am	

		countertop and wall			
/am	<	Caulk between			
22Jun22	\$0	Kitchen- General-	Interval	148083	
0	<	sink sink stopper			
/am	1	General- Adjust right			
22Jun22	B	Master Ensuite-	Interval	148082	
	3	bathroom			
	E /	facuet in both		•	

Date Completed: Y 2 Sume 174

Homeowner Signature:

has been completed in a workman like manner. The Homeowner acknowledges and accepts all work B Rahu

Date Completed:

Trade &/or Service Tech.

Signature:

Print Name:

signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367. adhere to the appointment you have scheduled. Your service representative must have this form appointment time or date appear (below) on this form, it is your responsibility to arrange and Please schedule your Service Department to complete work on the above Lot. Should no

applied to the Company listed above. it's group of companies) the right to carry out any and all repairs. All costs incurred will be Failure to comply with this request within 10 business days will give Zancor Homes (and

Outstanding Deficiencies Reserve Of Country Trails - Phase: 1 - Lot: 8

<u>Date</u> Reported	<u>Type</u>	Number	Deficiency Description	<u>Trade</u> <u>Assigned</u>	Add Trade	Appointment Date	Item Completed	Initial
02Jun22	PDI	2	EXTERIOR- PAINT~NOT COMPLETE	Princeston Painting 147976	<u>Add</u>	22Jun22		
02Jun22	PDI	3	BASEMENT- NOTE:~DENT ON SEPARATE ENTRANCE DOOR BY BASEMENT	Princeston Painting 147977	Add	22Jun22		BD
02Jun22	PDI	4	KITCHEN- CABINETS~SCRATCH ON LOWER LEFT CABINET RIGHT OF GARBAGE BIN	New Image Kitchens 147985	<u>Add</u>	22Jun22		****
02Jun22	PDI	5	KITCHEN- CABINETS~ADJUST UPPER CABINET ABOVE HOOD FAN RIGHT AND AND UPPER RIGHT DOOR RIGHT OF HOOD FAN AND AT ISLAND	New Image Kitchens 147978	Add	22Jun22		and the second s
02Jun22	PDI	6	UPPER HALL- RAILING~VARNISH REQUIRED AT UPPER FLOOR RAILING 2) VARNISH REQUIRED SCRATCH AT NEWEL POST AT 2ND LANDING AT STAIRS TO 2ND FLOOR	Princeston Painting 147979	Add	22Jun22		- Marie de Control de
02Jun22	PDI	8	BEDROOM 2 ENSUITE- COUNTERTOPS~SIDE SPLASH RIGHT OF SINK LIFTING	New Image Kitchens 147980	Add	22Jun22	CONTRACTOR OF THE PROPERTY OF	>
02Jun22	PDI	9	BEDROOM 2 ENSUITE- FLOORING~ADJUST CARPET SHIM AT ENTRANCE TO SHARED BATH	<u>Quality</u> 147981	Add	22Jun22		**************************************
02Jun22	PDI	10	LAUNDRY ROOM- CABINETS~CRACK ON COUNTERTOP LEFT OF SINK	New Image Kitchens 147982	Add	22Jun22	4	
02Jun22	PDI	11	MASTER ENSUITE BATH- VANITY CABINETS~SMALL CHIP ON LOWER RIGHT CABINET BELOW RIGHT AND SINK AND BELOW LOWER RIGHT SINK LEFT DOOR	New Image Kitchens 147983	Add	22Jun22		. http://doi.org/1017
02Jun22	PDI	12	MASTER ENSUITE BATH- COUNTERTOPS~SCRATCH ON RIGHT MARBLE SIDE SPLASH	Redstone Marble 147984	Add	22Jun22		
07Jun22	Interval	1	Foyer- General- touch up chips on astracal at front door above hinge	Zancor - Brampton Warranty Service 148025	Add	22Jun22	alay and an analysis of the second se	
07Jun22	Interval	2	Foyer- General- Dent on front door right side noted on walkthrough at key pick up	Zancor - Brampton Warranty Service 148026	Add	22Jun22		
07Jun22	Interval	3	Main Hall- General- Small dent on drywall mud room left of door	Zancor - Brampton	Add	22Jun22		Lakabida ka

9/22, 9:57 A	IVI		Denote toy Officer List - Goot. Glock					
				Warranty Service 148027				
09Jun22	Interval	4	Bedroom 2 Ensuite- General- Touch up cracked trim	Zancor - Brampton Warranty Service 148078	Add	<u>22Jun22</u>		4.0
09Jun22	Interval	5	Powder Room- General- Small area in powder room missing grout	Zancor - Brampton Warranty Service 148079	Add	<u>22Jun22</u>		New York Control of the Control of t
09Jun22	Interval	6	Foyer- General- Front door required to be adjusted	Zancor - Brampton Warranty Service 148080	Add	<u>22Jun22</u>	A	Po
09Jun22	Interval	7	Bedroom 2 Ensuite- General- Caulk around facuet in both bathroom	Zancor - Brampton Warranty Service 148081	<u>Add</u>	<u>22Jun22</u>		Po
09Jun22	Interval	8	Master Ensuite- General- Adjust right sink stopper	Zancor - Brampton Warranty Service 148082	Add	<u>22Jun22</u>		BO
09Jun22	Interval	9	Kitchen- General- Caulk between countertop and wall	Zancor - Brampton Warranty Service 148083	Add	22Jun22	January ver	9 57

Homeowner Signature: Bland

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Date: JUNE 9/22
Zancor Service Technician: ROLLINGEN