Enrollment:

Purchaser Name: Bhumika Bhandari

Aakash Lalith Kumar

Phone Res:

Phone Bus: (647) 809-5773 Closing Date: June 23, 2022 ZANCOR HOMES Vendor / Builder:

Project: Zancor Homes (Parkview) Ltd.

Lot / Phase: Unit 45 (Block 8) / 1

Plan: Address: Municiaplity:

Inspection Date: June 10, 2022

Inspector: Gisella Fiore Page 1 of 2

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

## DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

## **OPERATING CONDITION**

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

MASTER ENSUITE BATH		
MIRROR	MIRROR NOT INSTALLED THROUGHOUT	 
	SHOWER GLASS NOT INSTALLED	 
COUNTERTOPS	SMALL CHIP ON LEFT COUNTERTOP EDGE	 
KITCHEN		
SINK/FAUCET/PLUMBING	PLUMBING AT ISLAND NOT INSTALLED	 
	COUNTERTOP NOT INSTALLED	 
CABINETS	SMALL CHIP ON GARBAGE PULL OUT DRAWER AT ISLAND LEFT OF SINK	 
FOYER/HALL		
STAIRS	2ND COAT OF VARNISH NOT COMPLETE	 
UPPER HALL		
WALLS	CLOSET RACKS NOT INSTALLED THROUGHOUT	 
BASEMENT		
COLD ROOM	FLOOR DRAIN NOT INSTALLED IN COLD ROOM	 
EXTERIOR		
DECK	NOT INSTALLED AT REAR OF HOME AT FAMILY ROOM	 
NOTE:	AC NOT INSTALLED	 
GARAGE DOORS	NOT INSTALLED	 

Enrollment:

Purchaser Name: Bhumika Bhandari

Aakash Lalith Kumar

Phone Res:

Phone Bus: (647) 809-5773

Closing Date: June 23, 2022

Inspector: Gisella Fiore



Vendor / Builder:

Project: Zancor Homes (Parkview) Ltd.

Purchaser's Signature

Lot / Phase: Unit 45 (Block 8) / 1

Plan: Address: Municiaplity:

Inspection Date: June 10, 2022

Page 2 of 2

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

\* Purchases or owners who intend to configurate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to climb the form on their body.

designate to sign this form on their behalf.

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

Bhumika Bhandari

Purchaser's Name (print)

Purchaser's Signature

Aakash Lalith Kumar

Purchaser's Name (print)

Purchaser's Name (print)

Gisella Fiore

Designate's Name (print)

Designate's Signature

Inspector's Name (print)

Inspector's Signature

Date (YYYY/MM/DD) 2022/06/10 June 10, 2022