Enrollment:

Purchaser Name: Deep Jayantkumar Desai

Jayantkumar, S Desai

Phone Res:

Phone Bus: (416) 206-4699 Closing Date: July 14, 2022 Inspector: Gisella Fiore



Vendor / Builder:

Project: Zancor Homes (Brampton) Ltd.

Lot / Phase: 5 / 1 Plan: Address: Municiaplity:

Page 1 of 2 Inspection Date: June 28, 2022

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

MASTER BEDROOM			
FLOORING	CARPET SHIM NOT COMPLETE THROUGHOUT / H.O REQUEST TO INSPECT CARPET IN MASTER		
	BEDROOM BETWEEN TRIM AND FLOOR NOT TUCKED PROPERLY		
KITCHEN			
FLOORING	TILE NOT CUT FOR HEAT REGISTER IN KITCHEN / TILE CRACKED LEFT OF IT		
CABINETS	HOOD FAN NOT CONNECTED		
	SMALL CHIP ON UPPER RIGHT GABLE RIGHT HOOD FAN		
FOYER/HALL			
WINDOWS	DENT ON MAN DOOR AT DOOR AT STAIRS TO BASEMENT		
STAIRS	2ND COAT OF VARNISH REQUIRED ON STAIRS		
TRIM	FRONT DOOR RIGHT FIX DOOR HANDLE NOT INSTALLED		
	ASTRICAL AT FRONT DOOR CHIPPED		
EXTERIOR			
PAINT	EXTERIOR PAINTING NOT COMPLETE		
DECK	LEFT POST CRACKED		
UPPER HALL			
FLOORING	SCRATCH ON 2ND 3RD 4TH 5TH PLANK AT UPPER HALL BY NOSING AT STAIRS		
WALLS	LINE IN STIPPLE CEILING AT UPPER FLOOR ABOVE STAIRS		
MASTER ENSUITE BATH			
COUNTERTOPS	SMALL CHIP BELOW LOWER RIGHT CABINET INSIDE AT GABLE		
TUB	ADJUST TUB STOPPER NOT HOLDING WATER		
VANITY CABINETS	SMALL CHIP INSIDE LOWER LEFT CABINET AT GABLE		
BEDROOM #3			
WINDOWS	INSPECT MIDDLE FIXED WINDOW FOR SCRATCH AT EXTERIOR	-	

Enrollment:

Purchaser Name: Deep Jayantkumar Desai

Jayantkumar, S Desai

SMALL SCRATCH ON LEFT HANDLE BELOW LEFT SINK

2022/06/28

FLOOR DRAIN NOT INSTALLED LEFT UPSTAIRS BY COLD ROOM. AS PER CLIENT

Phone Res:

BEDROOM 3 ENSUITE
VANITY CABINETS

BASEMENT

Date (YYYY/MM/DD)

Phone Bus: (416) 206-4699
Closing Date: July 14, 2022
Inspector: Gisella Fiore



Vendor / Builder:

Project: Zancor Homes (Brampton) Ltd.

Lot / Phase: 5 / 1 Plan:

Address: Municiaplity:

Page 2 of 2 Inspection Date: June 28, 2022

A REFERENCE FOR FUTURE WARF	RANTY REQUESTS. o designate someone to conduct the PDI in the	E HOME'S CONDITION BEFORE THE PURCHAS	
I have inspected my new home and I	agree that the description of the items listed	on this form are accurate.	
Deep Jayantkumar Desai	4	Jayantkumar, S Desai	
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature
		Gisella Fiore	LA C
Designate's Name (print)	Dosignato's Signature	Inchestor's Name (print)	Inspector's Signature

June 28, 2022