Enrollment:

Purchaser Name: Original Purchaser Shaiba Nazir

Eldaniz Asadov

Phone Res: (905) 832-7696
Phone Bus: (416) 826-0506
Closing Date: July 21, 2022
Inspector: Gisella Fiore



Page 1 of 2

Vendor / Builder:

Project: Zancor Homes (Parkview) Ltd.

Lot / Phase: Unit 5 (Block 1) / 1

Plan: Address: Municiaplity:

Inspection Date: July 19, 2022

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

| MASTER ENSUITE BATH | | | |
|----------------------|---|-------|--|
| VANITY CABINETS | DENT ON RIGHT CABINET BELOW RIGHT SINK | _ | |
| NOTE: | RIGHT FIXED GLASS CRACKED | - | |
| UPPER HALL | | | |
| NOTE: | LINE ON CEILING BY LIGHT FIXTURE AT STIPPLE | _ | |
| BEDROOM 2 ENSUITE | | | |
| COUNTERTOPS | CHIP ON LEFT COUNTERTOP LIP BELOW ELECTRICAL OUTLET | = | |
| BEDROOM #2 | | | |
| FLOORING | FLOOR SQUEAK AT ENTRANCED TO 2ND BEDROOM LEFT SIDE | = | |
| BEDROOM #3 | | | |
| FLOORING | FLOOR SQUEAK AT ENTRANCED TO 3RD BEDROOM LEFT SIDE | = | |
| FOYER/HALL | | | |
| STAIRS | EXPOSED SCREWS AT RISER BELOW NOSING AT 3RD FLOOR / EXPOSED STAPLE AT RISER BELOW NOSING AT LANDING AT STAIRS TOO 3RD FLOOR / CRACK ON 2ND RISER AT STAIRS FROM LANDING FROM 2ND FLOOR TO 3RD FLOOR / CHIP ON 7TH TREAD BY RISER AT STAIRS FROM MAIN FLOOR TOO 3RD FLOOR / TREAD TO BE CUT STICKING OUT OF DINNING AREA / CHIP ON INSIDER STRINGER AT STAIRS FROM LANDING OF MAIN FLOOR TOO 2ND FLOOR | _ | |
| KITCHEN | | | |
| SINK/FAUCET/PLUMBING | PLUMBING AT ISLAND NOT COMPLETE | _ | |
| CABINETS | CHIP ON UPPER SHELF AT CABINET RIGHT OF HOOD FAN | _ | |
| POWDER ROOM | | | |
| SINK/FAUCET/PLUMBING | TOILET NOT LEVELLED AT MAIN FLOOR | _ | |
| LAUNDRY ROOM | | | |
| NOTE: | DENT ON MAN DOOR TO GARAGE | _ | |
| EXTERIOR | | | |
| GARAGE DOORS | NOT INSTALLED | _ | |
| NOTE: | AC NOT INSTALLED AT EXTERIOR | _ | |

Enrollment:

Purchaser Name: Original Purchaser Shaiba Nazir

Eldaniz Asadov

Phone Res: (905) 832-7696 Phone Bus: (416) 826-0506 Closing Date: July 21, 2022 Inspector: Gisella Fiore

ZANCOR

Vendor / Builder:

Project: Zancor Homes (Parkview) Ltd.

Lot / Phase: Unit 5 (Block 1) / 1

Plan: Address: Municiaplity:

Inspection Date: July 19, 2022

Page 2 of 2

| A REFERENCE FOR FUTURE WARRAN | ITY REQUESTS. esignate someone to conduct the PDI in th | E HOME'S CONDITION BEFORE THE PURCHASE weir place should ensure they provide written authors | |
|---------------------------------------|---|---|--|
| I have inspected my new home and I ag | gree that the description of the items listed | on this form are accurate. | |
| Original Purchaser Shaiba Nazir | | Eldaniz Asadov | |
| Purchaser's Name (print) | Purchaser's Signature | Purchaser's Name (print) | Purchaser's Signature |
| | MNG | Gisella Fiore | The state of the s |
| Designate's Name (print) | Designate's Signature | Inspector's Name (print) | Inspector's Signature |
| Date (YYYY/MM/DD) | 2022/07/19 | July 19, 2022 | |