Enrollment:

Purchaser Name: Gurnek, Singh Sandhu

Baljinder Kaur

Phone Res: (647) 205-7502 Phone Bus: (905) 672-0407 Closing Date: July 21, 2022

ZANCOR

Vendor / Builder:

Project: Zancor Homes (Brampton) Ltd.

Lot / Phase: 1/1

Plan: Address:

Municiaplity:

Inspection Date: July 18, 2022

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- Bathroom accessories if provided
- · Mirrors, counter tops and cabinetry
- · Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- · Interior finished and trim carpentry
- Fumace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- . Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- · Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- · Gas fireplaces, incl.circulation fans, if provided
- · Heat Recovery Ventilation system, if provided
- Heating system
- · Hot water heater, if provided (not rental)
- · Air conditioning system, if provided and if conditions permit

KITCHEN			
CABINETS	SMALL CHIP INSIDE LOWER CABINET AT BOTTOM GABLE LEFT OF BANK OF DRAWERS		
	CHIP ON GABLE AT UPPER CABINET LEFT OF STOVE		
	INSPECT MARK ON LEFT SIDE OF ISLAND LEFT OF SINK	Done.	XGIS S
FOYER/HALL		675	5.5
STAIRS	EXPOSED STABLE AT 6TH RISER AT STAIRS FROM MAIN FLOOR TOO LANDING TO 2ND FLOOR		200
	VARNISH REQUIRED AT NOSING AT 2ND FLOOR / VARNISH REQUIRED AT NEWEL POST AT MAIN	Done	X G SS
	FLOOR AT STAIRS TO 2ND FLOOR		
	DENT NOT 5TH AND 6TH TREAD AT STAIRS FROM MAIN FLOOR TOO LANDING TOO 2ND FLOOR /		
	DENT ON 3RD TREAD AT STAIRS FROM BASEMENT TO 2ND FLOOR FROM LANDING		
MASTER BEDROOM		Sq.	
WALLS	ADJUST DOORS TO MASTER CANNOT OPEN OR CLOSE DUE TO CARPET / ADJUT CLOSET	Done	X GS.S
	DOORS IN BEDROOM 3 AS WELL HITTING CARPET / INSPECT CARPETS AND DOORS		
	THROUGHOUT UPPER FLOOR VERY TIGHT		
BEDROOM 2 ENSUITE			
VANITY CABINETS	CHIP INSIDE LOWER LEFT VANITY AT GABLE		
	CHIP ON RIGHT COUNTERTOP EDGE RIGHT OF SINK		
UPPER HALL			
FLOORING	CHIP ON 11TH PLANK INFRONT OF BEDROOM INFRONT OF STAIRS		
POWDER ROOM			
NOTE:	CHIP ON GABLE LEFT SIDE		

Brampton