Enrollment:

Purchaser Name: Gloria E Holder

Sherville Holder

Phone Res:

Phone Bus: (289) 242-2921 Closing Date: May 19, 2022

HOMES

Page 1 of 2

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 22A / 1 Plan:

Address: Municiaplity:

Inspection Date: July 27, 2022

Inspector: Gisella Fiore

selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be

## DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

## **OPERATING CONDITION**

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

KITCHEN		
WALLS	BACKSPLASH NOT INSTALLED	 
CABINETS	CHIP ON UPPER RIGHT GABLE RIGHT OF HOOD FAN	 
	CHIP INSIDE LOWER CABINET AT SINK LEFT SIDE	 
	CHIP ON UPPER RIGHT CABINET ABOVE FRIDGE RIGHT SIDE	 
	CHIP ON UPPER LEFT CABINET BY WINDOW	 
	SMALL CHIP ON UPPER RIGHT FILLER RIGHT OF HOOD FAN	 
FLOORING	FILL NAIL HOLES IN LIVING AREA RIGHT AND LEFT OF KITCHEN	 
MASTER ENSUITE BATH		
SHOWER ENCLOSURE	SMALL CHIP ON MARBLE SURROUND RIGHT SIDE OF SHOWER DOOR	 
FLOORING	SMALL CHIP ON WALL TILE BEHIND FAUCET IN SHOWER	 
UPPER HALL		
FLOORING	SMALL CHIP ON THRESHOLD TO WASHROOM	 
BEDROOM #3		
FLOORING	CHIPPED	 
BEDROOM #4		
FLOORING	CARPET SHIM REQUIRED	 
BEDROOM 4 ENSUITE		
COUNTERTOPS	CHIP ON RIGHT COUNTERTOP EDGE AND LEFT OF SINK	 
BEDROOM #5		
NOTE:	STIPPLING PEELING LEFT OF LIGHT FIXTURE AND ABOVE WINDOW	 
FOYER/HALL		
STAIRS	SMALL DENT ON NOSING AT LANDING TOO 2ND FLOOR 2) DENT ON 2ND AND 3RD TREAD AT	 
	STAIRS FROM MAIN FLOOR TOO 2ND FLOOR	
	TOUCH UP REQUIRED AT OUTSIDE STRINGER AT RISERS AT STAIRS TOO 2ND FLOOR AT	 
	EDGES	

Enrollment:

Designate's Name (print)

Date (YYYY/MM/DD)

Purchaser Name: Gloria E Holder

Sherville Holder

Phone Res:

Phone Bus: (289) 242-2921
Closing Date: May 19, 2022
Inspector: Gisella Fiore



Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Inspector's Signature

Lot / Phase: 22A / 1

Plan:

Address: Municiaplity:

Page 2 of 2 Inspection Date: July 27, 2022

Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature	
Gloria E Holder	SW-K	Sherville Holder		
I have inspected my new h	ome and I agree that the description of the items listed	d on this form are accurate.		
A REFERENCE FOR FUTU	ILIVERY INSPECTION IS A FORMAL RECORD OF THE WARRANTY REQUESTS.  o intend to designate someone to conduct the PDI in on their behalf.			
THE COMPLETED DDE DE	U IVERVI MOREOTIONIO A FORMAL REGORD OF T	IE HONE'S CONDITION PEROPE THE PURCH	MOSE TAKES DOOGSOON TWILL BE	LIOED AO
NOTE:	SECURE ELECTRICAL OUTLET AT BACK OF	HOUSE		
RAILING	CRACK RAILING CAP LEFT SIDE AT FRONT I	PORCH		
PORCH	CHIP ON FIRST TREAD			<del></del>
PAINT	EXTERIOR PAINT NOT COMPLETE			
WINDOWS EXTERIOR	BOWED MAN DOOR RIGHT SIDE AT TOP CO	HINEH		
LAUNDRY ROOM	DOWED MAN DOOD BIGUT OUDS AT TOR OO	DNED		
FLOORING	CARPET SHIM REQUIRED AT ENSUITE ON M	IAIN FLOOR		
MAIN BATHROOM				
FLOORING	CHIP ON 7TH AND 9TH PLANK FROM RIGHT	WALL		
LIVING ROOM				
	X 2CHIP ON 4TH HARDWOOD PLANK FRONT	OF STAIRS TO BASEMENT FROM WALL		
FLOORING	SCRATCH ON 6TH AND 7TH PLANK FROM PO	OWDER ROOM BY REGISTER		

Inspector's Name (print)

July 27, 2022

Designate's Signature

2022/07/27