



Zancor Homes (Parkview) Ltd.

Warranty Services

Phone: (905) 738-7010

Fax: (905) 738-5948

Work Order

Closing Date: 20May22

Address:

Location:

Now Towns In Brooklyn - Phase: 1 - Lot: Unit 27 (Block 5)

21Jul22

Today's Date:

Contact(s): Ziyad, Tanweer Syed - Cell: (226) 808-7933 - (ziyad.syed@gmail.com)

Email:

ziyad.syed@gmail.com

Company:

Zancor - Brooklyn Warranty Service

Attention:

Telephone:

Fax:

Please Complete the following items:

DAI	Type	Issue		Appt. Date/Time	Notes
147366	PDI	Library- General- HUMP IN FRONT OF AIR RETURN BY MUDROOM		28Jul22 /am	
148585	30-Day	Main Hall- General- Item #1- scuff marks on the wall paint throughout main floor , marked with green tape hall and rooms on main floor including closets	✓	28Jul22 /am	
148586	30-Day	Main Hall- General- Item #2- trim multiple marks on main entrance door, the frosted window and the trim around the door that needs to be fixed marked with tape	✓	28Jul22 /am	
148587	30-Day	Main Hall- General- ITEM #3- scuff marks on the wall and trim is chipped in places and gap in the trim	✓	28Jul22 /am	

REBOOK FULL DAY FOR NOW

148588	30-Day	Main Hall- General- Item #4- There are multiple cracks on the walls in the main hallway closet, there are also screw holes that are visible behind the rack that was installed on the wall and ceiling in closet	✓	28Jul22 /am	
148589	30-Day	Main Hall- General- Item #5- there are scuff marks on the trim and paint chipped off in the closet and gap in trim and tile needs caulking and marks on the wall.	✓	28Jul22 /am	
148590	30-Day	Main Hall- General- Item #6- there is cracking in the ceiling inside the closet on the main floor as well as trim in side the closet	✓	28Jul22 /am	
148591	30-Day	Main Hall- General- Item #7- there are scuff marks and chips on the paint in the living room on the main floor, also the pain wasn't floor applied appropriately since areas are yellow and do not have a full coat on paint on it	✓	28Jul22 /am	
148592	30-Day	Main Hall- General- Item 8- multiple scuff marks on the wall in the bathroom - around the light fixture., the toilet the big wall and around the pedestal sink.	✓	28Jul22 /am	
148593	30-Day	Main Bathroom-		28Jul22	

		General- Item 9- paint chipped off can see yellow paint underneath , an appropriate coat and paint wasn't provided IN bathroom on main floor	/am	
148594	30-Day	Main Bathroom- General- item #10- toilet not fixed to be floor, can see the tile chips and discoloration underneath the toilet, this is visible upon walking into the bathroom/	28Jul22 /am	
148595	30-Day	Main Bathroom- General- Item #11- cracks on walls and ceiling inside the main floor powder room are visible.	28Jul22 /am	
148596	30-Day	Main Bathroom- General- item #12- big hole in the dry wall behind the pedestal sink in the main floor powder room	28Jul22 /am	
148597	30-Day	Den- General- Item #13- multiple marks on wall and paint chipped off that is marked with green tape in the living room of the main floor , and chips on the trim on the main floor by the stairs	28Jul22 /am	
148599	30-Day	Den- General- item #15- electrical outlet by the backyard doors is installed unevenly and is not flush on the wall	28Jul22 /am	
148600	30-Day	Den- General- item #16- multiple chips on	28Jul22 /am	

148601	30-Day	the trim and spacing between the trim and main floor living room	✓	28Jul22 /am	
148602	30-Day	Laundry Room- General- item #17- the trim/tiles not caulked properly as there is some residue and yellow colorings showing on the top of trim/tile in the laundry room	✓	28Jul22 /am	
148603	30-Day	Laundry Room- General- item #18- multiple scuffs marks on the paint on the walls and paint on hard wood	✓	28Jul22 /am	
148605	30-Day	Den- General- item #19- electrical outlets in the main floor living room on the right wall are painted over	✓	28Jul22 /am	
148607	30-Day	Stairs- General- item #21- there are chips on hardwood floor and ad there is paint marks on railing pickets and floors and stairs	✓	28Jul22 /am	
148608	30-Day	Dining Room- General- 23- there are scuff marks and chops on glass and trim around the dining room windows	✓	28Jul22 /am	
	30-Day	Dining Room- General- 24- the trim is not caulked properly , areas where there is a big gap between the floor and the molding at the bottom- not warranted we do not caulk between the floor and trim	✓	28Jul22 /am	

148609	30-Day	Shared Bathroom- General- item 25- small hole on ceiling on the 2nd floor powder room	28Jul22 /am	
148610	30-Day	Shared Bathroom- General- item 26- multiple cracks on the trims corners not caulked and there is a big gap that is visible between and door trim also a gap between molding and tile - tile was cut short	28Jul22 /am	
148611	30-Day	Kitchen- General- item 27- there are multiple scuff marks on the walls	28Jul22 /am	
148612	30-Day	Kitchen- General- item 28- the trim was not caulked properly similar to dining room there is a gap between the floor and the molding at the bottom	28Jul22 /am	
148613	30-Day	Kitchen- General- item 29- there is an uneven spacing between the tiles and some gap in the bar area	28Jul22 /am	
148614	30-Day	Kitchen- General- item 30- scuff marks on cabinets multiple cabinets had that issue	28Jul22 /am	
148615	30-Day	Kitchen- General- item 31- electrical outlet on the right side of the island is filled needs to be fixed	28Jul22 /am	
148616	30-Day	Living Room- General- item 32- the molding was not caulked properly multiple areas	28Jul22 /am	

148618	30-Day	with big gap between floor and molding at the bottom not warranted we do not caulk between the floor and trim	✓	28Jul22 /am	
		Living Room- General-item 33- trim around the windows and not completely properly , multiple scuffs chips between the window and trim- Chipped trim only we do not caulk between window and trim	✓		
148619	30-Day	Stairs- General- item 34- plenty of stairs with paint droplets on the multiple railings on the stairs 1st floor 2nd and 3rd	✓	28Jul22 /am	
148620	30-Day	Stairs- General- item 35- trim not caulked properly there are multiple paint marks on the stairs railings and trim	✓	28Jul22 /am	
148621	30-Day	Other- General- item 36- landing- multiple paint marks on the landing areas with hardwood railing	✓	28Jul22 /am	
148622	30-Day	Bedroom 2- General-item 37- windows- lots of paint marks and chips on windows and trim trim is not caulked properly mini holes as well , all over rooms	✓	28Jul22 /am	
148623	30-Day	Bedroom 2- General-item 38- closets scuff marks on walls and paint coming from multiple places in all the bedroom and	✓	28Jul22 /am	

148624	30-Day	closets including master		28Jul22 /am	
		Bedroom 2- General- item 39- there are scuff marks on shared bathroom tub and tiles they are multiple marks on them			
148625	30-Day	Main Bathroom- General- item 40- tub and tiles have multiple marks on them		28Jul22 /am	
148626	30-Day	Shared Bathroom- General- item 41- doors- there are marks on shared bathroom doors	✓	28Jul22 /am	
148627	30-Day	Bedroom 2- General- item 42- multiple bedrooms, holes chips and marks on window, caulking not done properly.	✓	28Jul22 /am	
148628	30-Day	Bedroom 2- General- item 43- trim- in master not installed and there are lots of gaps		28Jul22 /am	
148629	30-Day	Master Bedroom- General- item 44- closet- not installed is not straight or caulked properly there are multiple scuff marks on walls	✓	28Jul22 /am	
148630	30-Day	Master Bedroom- General- item 45- same issue with the windows in the master bedroom lots of chipped paint and marks on windows and haps between window and trim	✓	28Jul22 /am	
148632	30-Day	Master Ensuite-		28Jul22	

		General- item 47- shower- the grout a lot darker in some places		/am	
148633	30-Day	Master Bedroom- General- item 48- scuff marks on walls in master bedroom	✓	28Jul22 /am	
148634	30-Day	Master Bedroom- General- item 49- windows- sliding door to balcony has wires ticking out and there is gaps and not caulked	✓	28Jul22 /am	
148635	30-Day	Master Bedroom- General- item 50- the deck on master balcony seems to be on slant(N/A AS PER DRAWING)	✓	28Jul22 /am	
148636	30-Day	Master Bedroom- General- item 51- trim- gaps across al the doors and closet doors in all of the bedrooms upstairs	✓	28Jul22 /am	
148637	30-Day	Master Bedroom- General- item 51- gaps across all the doors and closets in all bedrooms	✓	28Jul22 /am	
148638	30-Day	Bedroom 2- General- Item 53- there are scuff marks across all walls in bedrooms and closets	✓	28Jul22 /am	
148639	30-Day	Exterior- General- item #53- on main door paint and scuff marks and side window the door trim and windows need to be cleaned		28Jul22 /am	
148640	30-Day	Exterior- General- item 54- door to the balcony on the second floor has black marks		28Jul22 /am	

148641	30-Day	on white trim Exterior- General- item 55- master balcony is slanted (N/A AS PER DRAWING)	28Jul22 /am	
148913	Interval	Master Bedroom- General- SVC TO INSPECT HUMP AT ENTRANCE TO CLOSET		

Date Completed: _____

Homeowner Signature: _____
The Homeowner acknowledges and accepts all work
has been completed in a workman like manner

Date Completed: Jul 28/22


Trade &/or Service Tech. _____
Signature: [Signature]
Print Name: ROBERT

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Now Towns In Brooklyn - Phase: 1 - Lot: Unit 27 (Block 5)

**147366 - 1 - FLOOR HUMP - HUMP IN FRONT OF
AIR RETURN BY MUDROOM**



**148605 - 1 - HARDWOOD 20 - item #21- there are
chips on hardwood floor and ad there is paint
marks on railing pickets and floors and stairs**



Outstanding Deficiencies
Now Towns In Brooklyn - Phase: 1 - Lot: Unit 27 (Block 5)

<u>Date Reported</u>	<u>Type</u>	<u>Number</u>	<u>Deficiency Description</u>	<u>Trade Assigned</u>	<u>Add Trade</u>	<u>Appointment Date</u>	<u>Item Completed</u>	<u>Initial</u>
<u>20Apr22</u>	PDI	2	Master Bedroom- General- HUMP UNDER CARPET AT ENTRANCE TO WALK IN CLOSET	Quality Rugs Canada LTD. 147355	Add	<u>28Jul22</u>	_____	
<u>20Apr22</u>	PDI	3	Master Bedroom- General- SCREEN DOOR NOT INSTALLED	Newmar 147356	Add	<u>28Jul22</u>	_____	
<u>20Apr22</u>	PDI	6	Bedroom 3- General- INSPECT UNDER CARPET LEFT OF OUTLET RIGHT SIDE FOR DEBRIS	Quality Rugs Canada LTD. 147359	Add	<u>28Jul22</u>	_____	
<u>20Apr22</u>	PDI	11	Living Room- General- DAMAGED DOOR JAMB BY HINGE AT BALCONY DOOR FRONT OF HOUSE	Newmar 147364	Add	<u>28Jul22</u>	_____	
<u>20Apr22</u>	PDI	12	Exterior- General- GARAGE DOORS NOT INSTALLED	Abbey Overhead Doors Inc. 147365	Add	<u>28Jul22</u>	✓	
<u>20Apr22</u>	PDI	13	Library- General- HUMP IN FRONT OF AIR RETURN BY MUDROOM	Zancor - Brooklyn Warranty Service 147366	Add	<u>28Jul22</u>	_____	
<u>12Jul22</u>	30-Day	1	Main Hall- General- Item #1- scuff marks on the wall paint throughout main floor , marked with green tape hall and rooms on main floor including closets	Zancor - Brooklyn Warranty Service 148585	Add	<u>28Jul22</u>	✓	
<u>12Jul22</u>	30-Day	2	Main Hall- General- Item #2- trim multiple marks on main entrance door, the frosted window and the trim around the door that needs to be fixed marked with tape	Zancor - Brooklyn Warranty Service 148586	Add	<u>28Jul22</u>	✓	
<u>12Jul22</u>	30-Day	3	Main Hall- General- ITEM #3- scuff marks on the wall and trim is chipped in places and gap in the trim	Zancor - Brooklyn Warranty Service 148587	Add	<u>28Jul22</u>	✓	
<u>12Jul22</u>	30-Day	4	Main Hall- General- Item #4- There are multiple cracks on the walls in the main hallway closet, there are also screw holes that are visible behind behind the rack that was installed on the wall and ceiling in closet	Zancor - Brooklyn Warranty Service 148588	Add	<u>28Jul22</u>	✓	
<u>12Jul22</u>	30-Day	5	Main Hall- General- Item #5- there are scuff marks on the trim and paint chipped off in the closet and gap in trim and tile needs caulking and marks on the wall.	Zancor - Brooklyn Warranty Service 148589	Add	<u>28Jul22</u>	✓	
<u>12Jul22</u>	30-Day	6	Main Hall- General- Item #6- there is cracking in the ceiling inside the closet on the main floor as well as trim in side the closet	Zancor - Brooklyn Warranty Service 148590	Add	<u>28Jul22</u>	✓	
<u>12Jul22</u>	30-Day	7	Main Hall- General- Item #7- there are scuff marks and chips on the paint in the living room on the main floor, also the pain wasn't floor applied appropriately since areas are yellow and do not have a full coat on paint on it	Zancor - Brooklyn Warranty Service 148591	Add	<u>28Jul22</u>	✓	
<u>12Jul22</u>	30-Day	8	Main Hall- General- Item 8- multiple scuff marks on the wall in the bathroom - around the light fixture, the toilet the big wall and around the pedestal sink.	Zancor - Brooklyn Warranty Service 148592	Add	<u>28Jul22</u>	✓	
<u>12Jul22</u>	30-Day	9	Main Bathroom- General- Item 9- paint chipped off can see yellow paint underneath , an appropriate coat and paint wasn't provided IN bathroom on main floor	Zancor - Brooklyn Warranty Service 148593	Add	<u>28Jul22</u>	✓	
<u>12Jul22</u>	30-Day	10	Main Bathroom- General- item #10- toilet not fixed to be floor, can see the tile chips and discoloration underneath the toilet, this is visible upon walking into the bathroom/	Zancor - Brooklyn Warranty Service 148594	Add	<u>28Jul22</u>	✓	
<u>12Jul22</u>	30-Day	11	Main Bathroom- General- Item #11- cracks on walls and ceiling inside the main floor powder room are visible.	Zancor - Brooklyn Warranty Service 148595	Add	<u>28Jul22</u>	✓	

<u>12Jul22</u>	30-Day	12	Main Bathroom- General- item #12- big hole in the dry wall behind the pedestal sink in the main floor powder room	Zancor - Brooklyn Warranty Service 148596	Add	<u>28Jul22</u>	✓
<u>12Jul22</u>	30-Day	13	Den- General- Item #13- multiple marks on wall and paint chipped off that is marked with green tape in the living room of the main floor , and chips on the trim on the main floor by the stairs	Zancor - Brooklyn Warranty Service 148597	Add	<u>28Jul22</u>	✓
<u>12Jul22</u>	30-Day	14	Den- General- Item #14- the top window trim installed is on the stant and is not straight,, both windows on the main floor are not straight @ bulkhead gap not even	MARCIANO DOORS AND TRIM 148598	Add	<u>28Jul22</u>	
<u>12Jul22</u>	30-Day	15	Den- General- item #15- electrical outlet by the backyard doors is installed unevenly and is not flush on the wall	Zancor - Brooklyn Warranty Service 148599	Add	<u>28Jul22</u>	✓
<u>12Jul22</u>	30-Day	16	Den- General- item #16- multiple chips on the trim and spacing between the trim and main floor living room	Zancor - Brooklyn Warranty Service 148600	Add	<u>28Jul22</u>	✓
<u>12Jul22</u>	30-Day	17	Laundry Room- General- item #17- the trim/tiles not caulked properly as there is some residue and yellow colorings showing on the top of trim/tile in the laundry room	Zancor - Brooklyn Warranty Service 148601	Add	<u>28Jul22</u>	✓
<u>12Jul22</u>	30-Day	18	Laundry Room- General- item #18- multiple scuffs marks on the paint on the walls and paint on hard wood	Zancor - Brooklyn Warranty Service 148602	Add	<u>28Jul22</u>	✓
<u>12Jul22</u>	30-Day	19	Den- General- item #19- electrical outlets in the main floor living room on the right wall are painted over	Zancor - Brooklyn Warranty Service 148603	Add	<u>28Jul22</u>	
<u>12Jul22</u>	30-Day	20	Stairs- General- item 20- stariacase- there are hardwood floor chipped off the floors of the house that need to be fixed nails and drill holes on stairs	Stairfab 148604	Add	<u>28Jul22</u>	
<u>12Jul22</u>	30-Day	21	Stairs- General- item #21- there are chips on hardwood floor and ad there is paint marks on railing pickets and floors and stairs	Zancor - Brooklyn Warranty Service 148605	Add	<u>28Jul22</u>	✓
<u>12Jul22</u>	30-Day	22	Dining Room- General- item 22- in the dining room door with access to deck there is large gap between the trim and door trim is damaged	MARCIANO DOORS AND TRIM 148606	Add	<u>28Jul22</u>	
<u>12Jul22</u>	30-Day	23	Dining Room- General- 23- there are scuff marks and chops on glass and trim around the dining room windows	Zancor - Brooklyn Warranty Service 148607	Add	<u>28Jul22</u>	✓
<u>12Jul22</u>	30-Day	24	Dining Room- General- 24- the trim is not caulked properly , areas where there is a big gap between the floor and the molding at the bottom- not warranted we do not caulk between the floor and trim	Zancor - Brooklyn Warranty Service 148608	Add	<u>28Jul22</u>	✓
<u>12Jul22</u>	30-Day	25	Shared Bathroom- General- item 25- small hole on ceiling on the 2nd floor powder room	Zancor - Brooklyn Warranty Service 148609	Add	<u>28Jul22</u>	✓
<u>12Jul22</u>	30-Day	26	Shared Bathroom- General- item 26- multiple cracks on the trims corners not caulked and there is a big gap that is visible between and door trim also a gap between molding and tile - tile was cut short	Zancor - Brooklyn Warranty Service 148610	Add	<u>28Jul22</u>	✓
<u>12Jul22</u>	30-Day	27	Kitchen- General- item 27- there are multiple scuff marks on the walls	Zancor - Brooklyn Warranty Service 148611	Add	<u>28Jul22</u>	✓
<u>12Jul22</u>	30-Day	28	Kitchen- General- item 28- the trim was not caulked properly similar to dining room there is a gap between the floor and the molding at the bottom	Zancor - Brooklyn Warranty Service 148612	Add	<u>28Jul22</u>	✓
<u>12Jul22</u>	30-Day	29	Kitchen- General- item 29- there is an uneven spacing between the tiles and some gap in the	Zancor - Brooklyn Warranty Service 148612	Add	<u>28Jul22</u>	

		bar area	Warranty. Service 148613			
<u>12Jul22</u>	30-Day	30	Kitchen- General- item 30- scuff marks on cabinets multiple cabinets had that issue	Add	<u>28Jul22</u>	
<u>12Jul22</u>	30-Day	31	Kitchen- General- item 31- electrical outlet on the the right side of the island is tiled needs to be fixed	Add	<u>28Jul22</u>	✓
<u>12Jul22</u>	30-Day	32	Living Room- General- item 32- the molding was not caulked properly multiple areas with big gap between floor and molding at the bottom not warranted we do not caulk between the floor and trim	Add	<u>28Jul22</u>	✓
<u>12Jul22</u>	30-Day	33	Living Room- General- item 33- trim around the windows and not completely properly , multiple scuffs chips between the window and trim- Chipped trim only we do not caulk between window and trim	Add	<u>28Jul22</u>	✓
<u>12Jul22</u>	30-Day	34	Stairs- General- item 34- plenty of stairs with paint droplets on multiple railings on the stairs 1st floor 2nd and 3rd	Add	<u>28Jul22</u>	✓
<u>12Jul22</u>	30-Day	35	Stairs- General- item 35- trim not caulked properly there are multiple paint marks on the stairs railings and trim	Add	<u>28Jul22</u>	✓
<u>12Jul22</u>	30-Day	36	Other- General- item 36- landing- multiple paint marks on the landing areas with hardwood railing	Add	<u>28Jul22</u>	✓
<u>12Jul22</u>	30-Day	37	Bedroom 2- General- item 37- windows- lots of paint marks and chips on windows and trim trim is not caulked properly mini holes as well , all over rooms	Add	<u>28Jul22</u>	✓
<u>12Jul22</u>	30-Day	38	Bedroom 2- General- item 38- closets scuff marks on walls and paint coming from multiple places in all the bedroom and closets including master	Add	<u>28Jul22</u>	✓
<u>12Jul22</u>	30-Day	39	Bedroom 2- General- item 39- there are scuff marks on shared bathroom tub and tiles they are multiple marks on them	Add	<u>28Jul22</u>	
<u>12Jul22</u>	30-Day	40	Main Bathroom- General- item 40- tub and tiles have multiple marks on them	Add	<u>28Jul22</u>	
<u>12Jul22</u>	30-Day	41	Shared Bathroom- General- item 41- doors- there ae marks on shared bathroom doors	Add	<u>28Jul22</u>	✓
<u>12Jul22</u>	30-Day	42	Bedroom 2- General- item 42- multiple bedrooms, holes chips and marks on window, caulking not done properly.	Add	<u>28Jul22</u>	✓
<u>12Jul22</u>	30-Day	43	Bedroom 2- General- item 43- trim- in master not installed and the are lots of gaps	Add	<u>28Jul22</u>	✓
<u>12Jul22</u>	30-Day	44	Master Bedroom- General- item 44- closet- not installed is not straight or caulked properly there are multiple scuff marks on walls	Add	<u>28Jul22</u>	✓
<u>12Jul22</u>	30-Day	45	Master Bedroom- General- item 45- same issue with the windows in the master bedroom lots of chipped paint and marks on windows and haps between window and trim	Add	<u>28Jul22</u>	✓
<u>12Jul22</u>	30-Day	46	Master Ensuite- General- item 46- master	Add	<u>28Jul22</u>	

			bath- trim is not installed properly behind the toilet cut short and big gap	<u>DOORS AND TRIM</u> 148631		✓
<u>12Jul22</u>	30-Day	47	Master Ensuite- General- item 47- shower- the grout a lot darker in some places	<u>Zancor - Brooklyn Warranty Service</u> 148632	Add <u>28Jul22</u>	
<u>12Jul22</u>	30-Day	48	Master Bedroom- General- item 48- scuff marks on walls in master bedroom	<u>Zancor - Brooklyn Warranty Service</u> 148633	Add <u>28Jul22</u>	✓
<u>12Jul22</u>	30-Day	49	Master Bedroom- General- item 49- windows- sliding door to balcony has wires ticking out and there is gaps and not caulked	<u>Zancor - Brooklyn Warranty Service</u> 148634	Add <u>28Jul22</u>	
<u>12Jul22</u>	30-Day	50	Master Bedroom- General- item 50- the deck on master balcony seems to be on slant(N/A AS PER DRAWING)	<u>Zancor - Brooklyn Warranty Service</u> 148635	Add <u>28Jul22</u>	✓
<u>12Jul22</u>	30-Day	51	Master Bedroom- General- item 51- trim- gaps across al the doors and closet doors in all of the bedrooms upstairs	<u>Zancor - Brooklyn Warranty Service</u> 148636	Add <u>28Jul22</u>	✓
<u>12Jul22</u>	30-Day	52	Master Bedroom- General- item 51- gaps across all the doors and closets in all bedrooms	<u>Zancor - Brooklyn Warranty Service</u> 148637	Add <u>28Jul22</u>	✓
<u>12Jul22</u>	30-Day	53	Bedroom 2- General- Item 53- there are scuff marks across all walls in bedrooms and closets	<u>Zancor - Brooklyn Warranty Service</u> 148638	Add <u>28Jul22</u>	✓
<u>12Jul22</u>	30-Day	54	Exterior- General- item #53- on main door paint and scuff marks and side window the door trim and windows need to be cleaned	<u>Zancor - Brooklyn Warranty Service</u> 148639	Add <u>28Jul22</u>	
<u>12Jul22</u>	30-Day	55	Exterior- General- item 54- door to the balcony on the second floor has black marks on white trim	<u>Zancor - Brooklyn Warranty Service</u> 148640	Add <u>28Jul22</u>	
<u>12Jul22</u>	30-Day	56	Exterior- General- item 55- master balcony is slanted (N/A AS PER DRAWING)	<u>Zancor - Brooklyn Warranty Service</u> 148641	Add <u>28Jul22</u>	
<u>18Jul22</u>	Interval	1	Master Bedroom- General- SVC TO INSPECT HUMP AT ENTRANCE TO CLOSET	<u>Zancor - Brooklyn Warranty Service</u> 148913	Add <u>No Appointment</u>	

Homeowner Signature:

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Date: July 28/22
Zancor Service Technician: [Signature]